


INSTRUCTION MANUAL



BK PRECISION
DYNASCAN CORPORATION

MODEL 1541A

40 MHz DUAL-TRACE OSCILLOSCOPE



BK PRECISION
DYNASCAN CORPORATION

SPECIFICATION TITTLE

METROLOGY CALIBRATION PROCEDURE
FOR THE

BK PRECISION 1541A



EQUIPMENT SERVICES CENTER

METROLOGY DEPARTMENT

PRODUCTION ENGINEERING - ESC

Prepared by		Date
Approved by Equipment Services Superintendentedent		Date
Approved by Equipment Services Manager		Date
Issue	Spec. No.  MCP0654	Sh. 01 of

THE UNIVERSITY OF CHICAGO
LIBRARY

BY THE UNIVERSITY OF CHICAGO

1913

THE UNIVERSITY OF CHICAGO
LIBRARY

ISSUE STATUS SPECIFICATION

EPC 900.

RELATED SPECIFICATIONS

CURRENT ISSUES & STATUS

EPC 900.

EPC 900. -EPS

N/A

EPC 900. -TRS

N/A

EPC 900. -RPS

N/A

EPC 900. -XRF

N/A

EPC 900. -PSS

N/A

EPC 900.000-CAL

METROLOGY CALIBRATION PROCEDURE



Prepared by

Technically Validated by

Approved by

STANDARDS LIST

NOTE: The equipment list below reflects the standards recommended by the calibration procedure of the UUT. Deviations from the recommended standards will be documented on this sheet.

RECOMMENDED STANDARDS	STANDARDS USED
1. The student will be able to identify the main idea of a paragraph.	
2. The student will be able to identify the supporting details of a paragraph.	
3. The student will be able to identify the topic sentence of a paragraph.	
4. The student will be able to identify the conclusion of a paragraph.	
5. The student will be able to identify the transition words used in a paragraph.	
6. The student will be able to identify the sentence structure used in a paragraph.	
7. The student will be able to identify the punctuation used in a paragraph.	
8. The student will be able to identify the capitalization used in a paragraph.	
9. The student will be able to identify the spelling used in a paragraph.	
10. The student will be able to identify the handwriting used in a paragraph.	

TEST INSTRUMENT SAFETY

WARNING

Normal use of test equipment exposes you to a certain amount of danger from electrical shock because testing must often be performed where exposed high voltage is present. An electrical shock causing 10 milliamps of current to pass through the heart will stop most human heartbeats. Voltage as low as 35 volts dc or ac rms should be considered dangerous and hazardous since it can produce a lethal current under certain conditions. Higher voltage poses an even greater threat because such voltage can more easily produce a lethal current. Your normal work habits should include all accepted practices that will prevent contact with exposed high voltage, and that will steer current away from your heart in case of accidental contact with a high voltage. You will significantly reduce the risk factor if you know and observe the following safety precautions:

1. Don't expose high voltage needlessly in the equipment under test. Remove housings and covers only when necessary. Turn off equipment while making test connections in high-voltage circuits. Discharge high-voltage capacitors after removing power.
2. If possible, familiarize yourself with the equipment being tested and the location of its high voltage points. However, remember that high voltage may appear at unexpected points in defective equipment.
3. Use an insulated floor material or a large, insulated floor mat to stand on, and an insulated work surface on which to place equipment; make certain such surfaces are not damp or wet.
4. Use the time-proven "one hand in the pocket" technique while handling an instrument probe. Be particularly careful to avoid contacting a nearby metal object that could provide a good ground return path.
5. When using a probe, touch only the insulated portion. Never touch the exposed tip portion.
6. When testing ac powered equipment, remember that ac line voltage is usually present on some power input circuits such as the on-off switch, fuses, power transformer, etc. any time the equipment is connected to an ac outlet, even if the equipment is turned off.
7. Some equipment with a two-wire ac power cord, including some with polarized power plugs, is the "hot chassis" type. This includes most recent television receivers and audio equipment. A plastic or wooden cabinet insulates the chassis to protect the customer. When the cabinet is removed for servicing, a serious shock hazard exists if the chassis is touched. Not only does this present a dangerous shock hazard, but damage to test instruments or the equipment under test may result from connecting the ground lead of most test instruments (including this oscilloscope) to a "hot chassis". To make measurements in "hot chassis" equipment, always connect an isolation transformer between the ac outlet and the equipment under test. The **B & K-Precision** Model TR-110 or 1604 Isolation Transformer, or Model 1653 or 1655 AC Power Supply is suitable for most applications. To be on the safe side, treat all two-wire ac powered equipment as "hot chassis" unless you are sure it has an isolated chassis or an earth-ground chassis.
8. Never work alone. Someone should be nearby to render aid if necessary. Training in CPR (cardio-pulmonary resuscitation) first aid is highly recommended.

Instruction Manual for



Model 1541A 40 MHz Dual-Trace Oscilloscope



6460 W. Cortland St. • Chicago, IL 60635
312-889-8870

TABLE OF CONTENTS

	Page
TEST INSTRUMENT SAFETY	Inside Front Cover
FEATURES.....	1
SPECIFICATIONS	3
CONTROLS AND INDICATORS	6
Front Panel Controls and Indicators.....	6
Rear Panel Controls	10
OPERATING INSTRUCTIONS.....	11
Safety Precautions	11
Equipment Protection Precautions.....	11
Operating Tips	12
Initial Starting Procedure	13
Single Trace Display	13
Dual Trace Display	13
Triggering.....	14
Single Sweep	16
X-Y Operation.....	17
External Horizontal Operation	17
Video Signal Observation	17
APPLICATIONS.....	19
DC Voltage Measurements.....	19
Measurements of Voltage Between Two Points on a Waveform.....	19
Add Mode Applications.....	20
Time Measurements	22
Frequency Measurements.....	23
Pulse Width Measurements	24
Pulse Rise Time and Fall Time Measurements	24
Time Difference Measurements	25
Phase Difference Measurements.....	26
Relative Measurements	27
X-Y Mode Applications	29
External Horizontal Sweep Applications	31
MAINTENANCE	32
Fuse Replacement.....	32
Case Removal	32
Line Voltage Selection	32
Periodic Adjustments	33
Calibration Check	33
Instrument Repair Service	33
APPENDIX I	
Important Considerations for Rise Time and Fall Time Measurements	34
WARRANTY SERVICE INSTRUCTIONS	35
LIMITED TWO-YEAR WARRANTY	36

FEATURES

HIGH FREQUENCY FEATURES

Wide Bandwidth

Conservatively rated -3 dB bandwidth is dc to 40 MHz.

Fast Rise Time

Rise time is less than 8.8 ns.

DUAL TRACE FEATURES

Dual Trace

Model 1541A has two vertical input channels for displaying two waveforms simultaneously. Selectable single trace (either CH 1 or CH 2) or dual trace. Alternate or chop sweep selectable at all sweep rates.

Sum and Difference Capability

Permits algebraic addition or subtraction of channel 1 and channel 2 waveforms, displayed as a single trace. Useful for differential voltage and distortion measurements.

CRT FEATURES

Rectangular CRT

Rectangular CRT with large 8 x 10 centimeter viewing area. Internal 8 x 10 division graticule eliminates parallax error.

Convenience

Variable scale illumination for easy viewing in darkened area and for waveform photographs. Trace rotation electrically adjustable from front panel. 0%, 10%, 90%, and 100% markers for rise time measurements.

VERTICAL FEATURES

High Sensitivity

5 mV/div sensitivity for full bandwidth. Selectable X5 gain increases maximum sensitivity to 1 mV/div at reduced bandwidth.

Calibrated Voltage Measurements

Accurate voltage measurements ($\pm 3\%$) on 10 calibrated ranges from 5 mV/div to 5 V/div. Vertical gain fully adjustable between calibrated ranges.

X5 Vertical Gain Magnification

X5 magnification control increases vertical sensitivity and adds 2 mV/div and 1 mV/div calibrated vertical attenuator ranges.

SWEEP FEATURES

Calibrated Time Measurements

Accurate ($\pm 3\%$) time measurements. Model 1541A has 20 calibrated ranges from 0.5 s/div to 0.2 μ s/div. Sweep time is fully adjustable between calibrated ranges.

X10 Sweep Magnification

Allows closer examination of waveforms, increases maximum sweep rate to 20 ns/div.

TRIGGERING FEATURES

Five Trigger Modes

Selectable automatic, normal (triggered), FIX, X-Y, or single sweep modes.

AUTO Sweep

Selectable AUTO sweep provides sweep without trigger input, automatically reverts to triggered sweep operation when adequate trigger is applied.

Triggered Sweep

Sweep remains at rest unless adequate trigger signal is applied. Fully adjustable trigger level and (+) or (-) slope.

FIX Trigger Level

Trigger level is automatically fixed on center of waveform.

X-Y Operation

Channel 1 can be applied as horizontal deflection (X-axis) while channel 2 provides vertical deflection (Y-axis).

SPECIFICATIONS

CRT:**Model:**

150BYB31.

Type:

Rectangular with internal graticule.

Display Area:

8 x 10 div(1 div = 1 cm).

Accelerating Voltage:

12 kV.

Scale Illumination:

Continuously adjustable.

VERTICAL AMPLIFIERS (CH 1 and CH 2)**Sensitivity:**

5 mV/div to 5 V/div.

1 mV/div to 1 V/div, X5 gain selected.

Accuracy:

5 mV/div to 5 V/div, $\pm 3\%$.

X5 gain selected, $\pm 5\%$.

Input Resistance:

1 M Ω $\pm 2\%$.

Input Capacitance:

Approximately 30 pF.

Frequency Response:

5 mV/div to 5 V/div (X5 gain not selected):

DC: DC to 40 MHz (-3 dB).

AC: 10 Hz to 40 MHz (-3 dB).

X5 gain selected:

DC: DC to 20 MHz (-3 dB).

AC: 10 Hz to 20 MHz (-3 dB).

Rise Time:

5 mV/div to 5 V/div (X5 gain not selected):

8.8 ns.

X5 gain selected:

17.5 ns.

Crosstalk:

At least 1000:1 (60 dB) at 50 kHz.

At least 30:1 (31.5 dB) at 40 MHz.

Operating Modes:

CH 1: CH 1, single trace.

CH 2: CH 2, single trace.

DUAL: dual trace.

0.5 s/div to 1 ms/div, CHOP.

0.5 ms/div to 0.2 μ s/div, ALT.

CHOP or ALT selectable at any sweep rate.

ADD: algebraic sum of CH 1 + CH 2.

Chop Frequency:

Approximately 250 kHz.

Polarity Reversal:

CH 2 only.

Maximum Input Voltage:

400 V (dc + ac peak) or 800 V ac p-p.

HORIZONTAL AMPLIFIER

(Input through channel 1 input)

X-Y mode: switch selectable using TIME/DIV switch.

CH 1: X axis.

CH 2: Y axis.

Sensitivity:

Same as vertical channel 1.

Accuracy:

Normal $\pm 4\%$, X5 Gain $\pm 6\%$.

Input Impedance:

Same as vertical channel 1.

Frequency Response:

DC to 2 MHz (-3 dB).

X-Y Phase Difference:

3° or less at 50 kHz.

Maximum Input Voltage:

Same as vertical channel 1.

HORIZONTAL AMPLIFIER

(Input through EXT TRIG input)

EXT Horizontal Mode:

Trace swept by external horizontal signal.

Vertical axis modes CH 1, CH 2, DUAL, and

ADD.

SPECIFICATIONS

Sensitivity:

Approximately 0.1 V/div.

Bandwidth:

DC to 2 MHz (-3 dB).

Phase Difference:

3° or less at 50 kHz.

Maximum Voltage:

100 V (dc + ac peak) to 1 kHz.

SWEEP SYSTEM

Sweep Speed:

0.2 μ s/div to 0.5 s/div in 1-2-5 sequence, 20 steps. Vernier control provides fully adjustable sweep time between steps.

Accuracy:

±3%.

Sweep Magnification:

10X, ±5% (±8% for 0.2 μ s/div and 0.5 μ s/div).

Linearity (for eight center divisions of sweep):

Norm ±3%.

X10 MAG ±5% (±8% for 0.2 μ s/div and 0.5 μ s/div).

Holdoff:

Continuously adjustable from NORM to 10 times normal.

TRIGGERING

Trigger Modes:

AUTO (free run), NORM, FIX, X-Y, SINGLE.

Trigger Source:

CH 1, CH 2, ALT, LINE, EXT.

Trigger Coupling:

AC 10 Hz to 40 MHz.
DC DC to 40 MHz.
HF REJ 10 Hz to 50 kHz.
TV Line automatically selected at 50 μ s/div and faster. Frame automatically selected at 0.1 ms/div and slower.

Trigger Sensitivity:

COUPLING	BANDWIDTH	INT	EXT
DC	DC - 10 MHz DC - 40 MHz	0.5 div 1.5 div	100 mV 200 mV
AC	Same as DC except increased attenuation below 10 Hz		
LF (HF REJ)	Same as AC except increased attenuation above 50 kHz.		
TV		2 div	200 mV
AUTO	Same as AC except lower limit is 50 Hz.		
FIX, ALT	Same as AC plus 0.5 div for signal of duty cycle 20:80 and repetition frequency of 50 Hz to 40 MHz.		

External Trigger:

Input Impedance:

1 M Ω ±2%, approximately 30 pF.

Maximum Input Voltage:

100 V (dc + ac peak) to 1 kHz.

OTHER SPECIFICATIONS

Calibrating Voltage:

1 kHz Positive Square Wave (±5%), 2 V p-p (±2%). Duty cycle of 50% ±2%.

Intensity Modulation:

Input Signal:

TTL level, intensity decreasing with more positive levels.

Input Impedance:

Approximately 5 k Ω .

Usable Frequency Range:

DC to 5 MHz.

Maximum Input Voltage:

100 V (dc + ac peak) to 1 kHz.

CH 1 Output (on rear panel):

Output Voltage:

50 mV/div (into 50-ohm load).

Output Impedance:

Approximately 50 ohms.

Frequency Response:

5 mV/div to 5 V/div:

100 Hz to 40 MHz, -3 dB, into
50 Ω .

1 mV/div and 2 mV/div:

100 Hz to 15 MHz, -3 dB, into
50 Ω .

Trace Rotation:

Electrical, front panel adjustable.

Power Requirements:

100 V/120 V/220 V/230 V/240 V $\pm 10\%$,
50/60 Hz, approximately 35 W.

Dimensions:

310 x 170 x 460 mm (13.4 x 5.7 x 15.0").

Weight:

7.1 kg (17.6 lb).

Operating Environment:

+10° to +35° C, 85% maximum relative
humidity for full specifications.

0° to +40° C, 85% maximum relative hum-
idity, full operating range.

SUPPLIED ACCESSORIES:

Two 10:1/Direct Probes.

Instruction Manual.

Schematic Diagram and Parts List.

OPTIONAL ACCESSORIES:

10:1 Probe, PR-45.

100:1 Probe, PR-100.

CONTROLS AND INDICATORS




Fig. 1. Front Panel Controls And Indicators.

FRONT PANEL CONTROLS AND INDICATORS

CRT CONTROLS

1. **POWER Switch.** Turns oscilloscope power on and off.
2. **POWER Indicator.** Lights when oscilloscope is on.
3. **INTENSITY Control.** Adjusts brightness of trace.
4. **FOCUS Control.** Adjusts sharpness of trace.
5. **TRACE ROTATION Control.** Screw-driver adjustment used to adjust trace to optimum horizontal position.
6. **Scale ILLUMINATION Control.** Adjusts intensity of oscilloscope scale. When control is fully counterclockwise, oscillo-

scope scale illumination is off. Clockwise rotation of the control increases the illumination of the graticule scale.

7. **CAL 2 V p-p Terminal.** This terminal provides a 1 kHz, 2-volt peak-to-peak square wave signal. This is useful for probe compensation adjustment and a general check of oscilloscope calibration accuracy.

CHANNEL 1 CONTROLS

8. **AC-GND-DC Switch.** Three-position lever switch which operates as follows:

AC:

Channel 1 input signal is capacitively coupled; dc component is blocked.

GND:

Opens signal path and grounds input to vertical amplifier. This provides a zero-volt base line, the position of which can be used as a reference when performing dc measurements.

DC:

Direct coupling of channel 1 input signal; both ac and dc component of signal produce vertical deflection.

9. **CH 1 (X) Jack.** Vertical input for channel 1. X axis input for X-Y operation.

10. **↕ CH1 POSition, PULL CHOP Control.**

↕ CH 1 POSition:

Rotation adjusts vertical position of channel 1 trace.

PULL CHOP (Push-Pull Switch):

Selects chop method of dual-trace display. When this control is pulled out and dual-trace is selected, both waveforms will be displayed simultaneously, regardless of **TIME/DIV** or **ALT** control settings. When this control is pushed in and dual-trace is selected, the display method (chop or alternate) is automatically selected by the **TIME/DIV** control (unless overridden by the **ALT** switch).

11. **VOLTS/DIV Control.** Vertical attenuator for channel 1. Provides step adjustment

of vertical sensitivity. When channel 1 **VAR** control is set to **CAL**, vertical sensitivity is calibrated in 10 steps from 5 mV/div to 5 V/div in a 1-2-5 sequence. In X-Y operation, this control provides step adjustment of X-axis sensitivity.

12. **VARiable, PULL X5 Control.**

VARiable:

Rotation provides vernier adjustment of channel 1 vertical gain. In the fully clockwise (**CAL**) position, the vertical attenuator is calibrated. In X-Y operation this control becomes the vernier X-axis gain control.

PULL X5 (Push-Pull Switch):

Multiplies channel 1 vertical gain five times; for example, 5 mV/div sensitivity becomes 1 mV/div.

13. **VERTical MODE Switch.**

CH 1:

Only the input signal to channel 1 is displayed on the CRT.

CH 2/X-Y:

Only the input signal to channel 2 is displayed on the CRT. Also, used in conjunction with **TIME/DIV** and trigger **SOURCE** switch to select X-Y operating mode.

DUAL:

The input signal to channel 1 and channel 2 are displayed simultaneously on two traces.

ADD:

The input from channel 1 and channel 2 are algebraically summed and displayed as a single signal. When the **CH 2 INV** function is activated, the input from channel 2 is subtracted from channel 1 and the difference is displayed as one signal.

CHANNEL 2 CONTROLS

14. **VOLTS/DIV Control.** Vertical attenuator for channel 2. Provides step adjustment of vertical sensitivity. When channel 2 **VAR** control is set to **CAL**, vertical sensitivity is calibrated in 10 steps from 5 mV/div to 5 V/div in a 1-2-5 se-

quence. In X-Y operation, provides step adjustment of Y-axis sensitivity.

15. VARIABLE, PULL X5 Control.

VARIABLE:

Rotation provides vernier adjustment of channel 2 vertical sensitivity. In the fully clockwise (**CAL**) position, the attenuator is calibrated. In X-Y operation this control becomes the vernier Y-axis gain control.

PULL X5 (Push-Pull Switch):

Multiplies channel 1 vertical gain five times; for example, 5 mV/div sensitivity becomes 1 mV/div.

16. CH2 POSITION, PULL INVERT Control.

CH2 POSITION:

Rotation adjusts vertical position of channel 2 trace. In X-Y operation, rotation adjusts vertical position of display.

PULL INVERT (Push-Pull Switch):

Selects inverse of normal polarity of channel 2 signal; inverted polarity when pulled out, normal polarity when pushed in.

17. CH 2 (Y) Jack. Vertical input for channel 2. Y-axis input in X-Y operation.

18. AC-GND-DC Switch. Three-position lever switch which operates as follows:

AC:

Channel 2 input signal is capacitively coupled; dc component is blocked.

GND:

Opens signal path and grounds input to vertical amplifier. This provides a zero-volt base line, the position of which can be used as a reference when performing dc measurements.

DC:

Direct coupling of channel 2 input signal; both ac and dc component of signal produce vertical deflection.

TRIGGERING CONTROLS

19. EXT TRIG Jack. External trigger input for single and dual-trace operation. Also serves as sweep input for external horizontal operation.

20. TRIGGER LEVEL, HOLD OFF Control.

TRIGGER LEVEL:

Trigger level adjustment, determines point on the triggering waveform where the sweep is triggered. Rotation in the (-) direction selects a more negative point of triggering, and rotation in the (+) direction selects a more positive point of triggering. When the control is rotated fully counterclockwise (**FIX**), the **FIX** triggering mode is selected. In the **FIX** triggering mode, the trigger threshold is automatically set at the center of the waveform.

HOLD OFF:

Rotation of control adjusts holdoff time (trigger inhibit period beyond sweep duration). When control is rotated fully counterclockwise, holdoff is set to **NORM**. Holdoff period increases progressively with clockwise rotation to a maximum of about 10 times normal.

21. TRIGGER SOURCE Switch. Selects source of sweep trigger. Four position lever switch with the following positions:

CH 1:

Channel 1 signal becomes sweep trigger for dual-trace operation (for single-trace operation, the channel displayed is the trigger signal unless the **LINE** or **EXT** position is selected).

CH 2:

Channel 2 signal becomes sweep trigger for dual-trace operation (for single trace operation, the channel displayed is the trigger signal unless the **LINE** or **EXT**, position is selected).

LINE:

Signal derived from the input line voltage (50/60 Hz) becomes trigger.

EXT:

Signal from **EXT TRIG** jack becomes sweep trigger.

22. TRIGGER COUPLING Switch. Selects trigger coupling. Four-position lever switch with the following positions:

AC:

Trigger is capacitively coupled; dc component is blocked.

HF REJ:

Trigger is coupled through low pass filter. Frequencies above 40 kHz are attenuated.

TV:

Vertical or horizontal sync pulses are selected. When sweep speeds of 0.1 ms/div or slower are selected, vertical sync pulses are selected. When sweep speeds of 50 μ s/div or faster are selected, horizontal sync pulses are selected.

23. **TRIGger SLOPE (-) Switch.** Two-position switch selects negative going or positive going trigger slope. When the switch is in (-) position, negative going (-) slope is selected and when the switch is in the (+) position, positive-going (+) slope is selected as the triggering point.
24. **ALT TRIG Switch.** Selects alternate trigger and alternate display mode when the switch is engaged and dual-trace display is selected. In the alternate trigger mode, the input signals alternate as the trigger source and triggering is impossible unless both input signals are of adequate level to trigger the sweep. In the alternate display mode when dual-trace display is selected, the waveforms will be displayed in an alternating fashion. However, if **PULL CHOP** control is in the pulled out position, **CHOP** display mode is selected (the **PULL CHOP** control overrides both the **TIME/DIV** and **ALT** setting) and the display cannot be synchronized since the chopping signal becomes the trigger source.

SWEEP CONTROLS

25. **SWEEP MODE Switches.** Three mechanically interactive switches used to select the desired triggering mode as follows:

AUTO:

Selects automatic triggering mode. Generates sweep (free runs) in absence of trigger; automatically reverts to triggered sweep operation

when adequate trigger signal is present.

NORM:

Selects normal triggered sweep operation, which generates a sweep only when adequate trigger signal is present. When the oscilloscope is set up for multiple trigger sources (dual-trace display with **ALT** triggering selected), both channels must have adequate trigger signals to obtain a sweep.

SINGLE:

Selects single sweep operation. For dual-trace display, single sweep requires **CHOP** method of display; do not select **ALT**. A single sweep will begin when the next sync trigger occurs. After a single sweep, **SINGLE** must be pressed again to enable next single sweep. Indicator (**READY LED**) lights to show that single sweep operation is ready for triggering. Lights when **SINGLE** switch is operated and remains lit until one sweep is completed.

26. **TIME/DIV Control.** Provides step selection of sweep rate. When the sweep time **VAR** control is set to the **CAL** position, sweep rate is calibrated. Control has 20 steps from 0.2 μ s/div to 0.5 s/div, in a 1-2-5 sequence. When control is rotated fully counterclockwise, **X-Y/EXT HOR** mode of operation is selected. If control is in **X-Y** position and trigger **SOURCE** switch is set to **CH 1/X-Y** position, oscilloscope is in **X-Y** operating mode. If control is in **X-Y** position and trigger **SOURCE** switch is set to **EXT** position, the signal connected to **EXT TRIG** jack controls sweep.

27. **SWEEP/VARIABLE, PULL X10 MAG Control.**

SWEEP/VARIABLE.:

Rotation of this control is the vernier adjustment for sweep rate. When the control is rotated fully clockwise (**CAL**), the sweep rate is calibrated.

PULL X10 MAG (Push-Pull Switch):

Selects ten times sweep magnification when pulled out (**X10 MAG**),

normal when pushed in. Expands sweep and increases maximum sweep rate to 20 ns/div.

28. **◀▶ POSition Control.** Horizontal position control. Adjusts horizontal position of display in all operating modes.

REAR PANEL CONTROLS

29. **GND Terminal.** Oscilloscope chassis ground and earth ground via 3-wire ac power cord.
30. **CH 1 OUT Jack.** Output terminal where sample of channel 1 signal is available. Amplitude is 50 millivolts per division of vertical deflection seen on CRT when terminated into 50 ohms. Output impedance is 50 ohms.

31. **Z AXIS INPUT Jack.** Input jack for intensity modulation of CRT electron beam. TTL compatible (5 volts p-p sensitivity). Positive signal levels decrease intensity.
32. **Fuse Holder.** Contains line fuse.
33. **Tilt Stand (not shown).**
34. **Feet/Cord Wrap.**




Fig. 2. Rear Panel Controls.

OPERATING INSTRUCTIONS

SAFETY PRECAUTIONS

WARNING

The following precautions must be observed to help prevent electric shock.

1. When the oscilloscope is used to make measurements in equipment that contains high voltage, there is always a certain amount of danger from electrical shock. The person using the oscilloscope in such conditions should be a qualified electronics technician or otherwise trained and qualified to work in such circumstances. Observe the TEST INSTRUMENT SAFETY recommendations listed on the inside front cover of this manual.
2. Do not operate this oscilloscope with the case removed unless you are a qualified service technician. High voltage up to 12,000 volts is present when the unit is operating with the case removed.
3. The ground wire of the 3-wire ac power plug places the chassis and housing of the oscilloscope at earth ground. Use only a 3-wire outlet, and do not attempt to defeat the ground wire connection or float the oscilloscope; to do so may pose a great safety hazard.
4. Special precautions are required to measure or observe line voltage waveforms with any oscilloscope. Use the following procedure:
 - a. Do not connect the ground clip of the probe to either side of the line. The clip is already at earth ground and touching it to the hot side of the line may "weld" or "disintegrate" the probe tip and cause possible injury, plus possible damage to the scope or probe.
 - b. Insert the probe tip into one side of the line voltage receptacle, then

the other. One side of the receptacle should be "hot" and produce the waveform. The other side of the receptacle is the ac return and no waveform should result.

EQUIPMENT PROTECTION PRECAUTIONS

CAUTION

The following precautions will help avoid damage to the oscilloscope.

1. Never allow a small spot of high brilliance to remain stationary on the screen for more than a few seconds. The screen may become permanently burned. A spot will occur when the scope is set up for X-Y operation and no signal is applied. Either reduce the intensity so the spot is barely visible, apply signal, or switch back to normal sweep operation. It is also advisable to use low intensity with AUTO triggering and no signal applied for long periods. A high intensity trace at the same position could cause a line to become permanently burned onto the screen.
2. Do not rest objects on top of the oscilloscope or otherwise obstruct the ventilating holes in the case, as this will increase the internal temperature.
3. Excessive voltage applied to the input jacks may damage the oscilloscope. The maximum ratings of the inputs are as follows:

CH 1 and CH 2:

800 V p-p; 400 V dc + ac peak.

EXT TRIG:

100 V dc + ac peak.

Z AXIS INPUT:

50 V dc + ac peak.



Never apply external voltage to oscilloscope output jacks.

4. Always connect a cable from the ground terminal of the oscilloscope to the chassis of the equipment under test. Without this precaution, the entire current for the equipment under test may be drawn through the probe clip leads under certain circumstances. Such conditions could also pose a safety hazard, which the ground cable will prevent.
5. The probe ground clips are at oscilloscope ground and should be connected only to the common of the equipment under test. To measure with respect to any point other than the common, use CH 1 - CH 2 subtract operation (ADD mode and CH 2 INV), with the channel 1 probe to the point of measurement and the channel 2 probe to the point of reference. Use this method even if the reference point is a dc voltage with no signal.
1. Always use the probe ground clips for best results, attached to a circuit ground point near the point of measurement. Do not rely solely on an external ground wire in lieu of the probe ground clips as undesired signals may be induced.
2. Avoid the following operating conditions:
 - a. Direct sunlight.
 - b. High temperature and humidity.
 - c. Mechanical vibration.
 - d. Electrical noise and strong magnetic fields, such as near large motors, power supplies, transformers, etc.
3. Occasionally check trace rotation, probe compensation, and calibration accuracy of the oscilloscope using the procedures found in the MAINTENANCE section of this manual.
4. Terminate the output of a signal generator into its characteristic impedance to minimize ringing, especially if the signal has fast edges such as square waves or pulses. For example, the typical 50 Ω output of a square wave generator should be terminated into an external 50 Ω terminating resistor and connected to the oscilloscope with 50 Ω coaxial cable.

OPERATING TIPS

The following recommendations will help obtain the best performance from the oscilloscope.




Fig. 3. Initial Control Settings.

5. Probe compensation adjustment matches the probe to the input of the scope. For best results, compensation should be adjusted initially, then the same probe always used with the same channel. Probe compensation should be readjusted when a probe from a different oscilloscope is used.

INITIAL STARTING PROCEDURE

Until you familiarize yourself with the use of all controls, the settings shown in Fig. 3 may be used as a reference point to obtain a trace on the CRT in preparation for waveform observation.

1. Engage the **POWER** switch; the unit will be turned on and the pilot light will be illuminated. Adjust scale illumination level with the **ILLUM** control. When the control is turned fully clockwise, the scale is illuminated at full brightness.
2. The controls should be set as follows; **VERT MODE** to **CH 1**, **SWEEP MODE** to **AUTO**, and **TRIG SOURCE** to **CH 1**.
3. A trace should appear on the CRT. Adjust the trace brightness with the **INTEN** control and the trace sharpness with the **FOCUS** control.

SINGLE TRACE DISPLAY

Either channel 1 or channel 2 may be used for single-trace operation. The advantage of using channel 2 is that the waveform on the display can be inverted if desired with the **PULL INV** switch.

1. Perform the steps of the "Initial Starting Procedure" with the **VERT MODE** switch set to **CH 2**.
2. Connect the probe to the **CH 2 (Y)** input jack.
3. Connect the probe ground clip to the chassis or common of the equipment under test. Connect the probe tip to the point of measurement.

4. If no waveforms appear, increase the sensitivity by turning the **CH 2 VOLTS/DIV** control clockwise to a position that gives 2 to 6 divisions vertical deflection.
5. The display on the CRT may be unsynchronized. Refer to the "Triggering" paragraphs in this section for procedures on setting triggering and sweep controls to obtain a stable display showing the desired number of waveforms.

DUAL TRACE DISPLAY

In observing simultaneous waveforms on channel 1 and 2, the waveforms are usually related in frequency, or one of the waveforms is synchronized to the other, although the basic frequencies are different. If the two waveforms have no phase or frequency relationship, there is seldom reason to observe both waveforms simultaneously. However, with **ALT** triggering, two waveforms not related in frequency or period can be simultaneously viewed.

1. Connect probes to both **CH 1 (X)** and **CH 2 (Y)** input jacks.
2. Connect the ground clips of the probes to the chassis or common of the equipment under test. Connect the tips of the probes to the two points in the circuit where waveforms are to be measured.
3. With the **ADD** function selected, the algebraic sum of **CH 1 + CH 2** is displayed as a single trace. When the **PULL INV** button is also engaged, the algebraic difference of **CH 1 - CH 2** is displayed.
4. To view both waveforms simultaneously, set the **VERT MODE** switch to **DUAL**.
5. When sweep times of 0.5 ms/div and faster are selected, the **ALT** display mode is automatically selected. When sweep times slower than 0.5 ms/div are selected, the **CHOP** display mode is automatically selected. It is possible to override the automatic selection by pulling out the **PULL CHOP** switch to select the **CHOP** display mode at all

sweep speeds or by pressing the **ALT TRIG** switch to select **ALT** display mode at all sweep speeds. However, do not engage **ALT** and **CHOP** display at the same time. Because selecting the **ALT** display mode also selects the **ALT TRIG** mode, selecting both **ALT** and **CHOP** simultaneously results in a display that cannot be synchronized since the chop signal itself becomes the trigger source. Use the **ALT** mode only, or select a trigger source of channel 1 or channel 2.

a. In the **ALT** mode, one sweep displays the channel 1 signal and the next sweep displays the channel 2 signal in an alternating sequence. Alternate sweep is normally used for viewing high-frequency or high-speed waveforms at sweep times of 1 ms/div and faster, but may be selected at any sweep time.

b. In the **CHOP** mode, the sweep is chopped at an approximate 250 kHz rate and switched between channel 1 and channel 2. Chop sweep is normally used for low-frequency or low-speed waveforms at sweep times of 1 ms/div and slower. If chop sweep is used at sweep times of 0.2 ms/div and faster, the chop rate becomes a significant portion of the sweep and may become visible in the displayed waveform. However, you may select chop sweep at any sweep time for special applications. For example, the only way to observe simultaneous events on a dual-trace scope at any sweep rate is with chop sweep.

6. Adjust the **CH 1** and **CH 2 POS** controls to place the channel 1 trace above the channel 2 trace.

7. Set the **CH 1** and **CH 2 VOLTS/DIV** controls to a position that gives 2 to 3 divisions of vertical deflection for each trace. If the display on the screen is unsynchronized, refer to the "Triggering" paragraphs in this section of the manual for procedures for setting triggering and

sweep time controls to obtain a stable display showing the desired number of waveforms.

TRIGGERING

The Model 1541A Oscilloscope provides versatility in sync triggering for ability to obtain a stable, jitter-free display in single-trace, or dual-trace operation. The proper settings depend upon the type of waveforms being observed and the type of measurement desired. An explanation of the various controls which affect synchronization is given to help you select the proper setting over a wide range of conditions.

SWEEP MODE Switches

1. The **NORM** switch provides normal triggered sweep operation. The sweep remains at rest until the selected trigger source signal crosses the threshold level set by the **TRIG LEVEL** control. The trigger causes one sweep to be generated, after which the sweep again remains at rest until triggered. In the **NORM** position, there will be no trace unless an adequate trigger signal is present. In the **ALT** mode of dual trace operation with **NORM** sweep selected, there will be no trace unless both channel 1 and channel 2 signals are adequate for triggering. Typically, signals that produce even 1/2 division of vertical deflection are adequate for normal triggered sweep operation.

2. When the **AUTO** switch is engaged, automatic sweep operation is selected. In automatic sweep operation, the sweep generator free runs to generate a sweep without a trigger signal. However, it automatically switches to triggered sweep operation if an acceptable trigger source signal is present. The **AUTO** position is handy when first setting up the scope to observe a waveform; it provides sweep for waveform observation until other controls can be properly set. Once the controls are set, operation is often switched back to the **NORM** triggering

mode, since it is more sensitive. Automatic sweep must be used for dc measurements and signals of such low amplitude that they will not trigger the sweep.

NOTE

In the **X-Y** mode, the sweep generator and triggering circuits are disconnected and have no effect.

TRIGger SOURCE Switch

The **TRIG SOURCE** switch **CH 1**, **CH 2**, etc.) selects the signal to be used as the sync trigger. In the single trace display mode (**VERT MODE** set to either **CH 1** or **CH 2**), the channel selected for display is automatically selected as the trigger source unless the **TRIG SOURCE** switch is set to the **LINE** or **EXT** position.

1. If the **TRIG SOURCE** switch is set to **CH 1** (or **CH 2**) the channel 1 (or channel 2) signal becomes the trigger source when **DUAL** or **ADD VERT MODE** is selected. **CH 1**, or **CH 2** is often used as the trigger source for phase or timing comparison measurements.
2. If the **TRIG SOURCE** switch is set to the **LINE** position, triggering is derived from the input line voltage (50/60 Hz). This is useful for measurements that are related to line frequency.
3. If the **TRIG SOURCE** switch is set to the **EXT** position, the signal applied to the **EXT TRIG** jack becomes the trigger source. This signal must have a timing relationship to the displayed waveform(s) for a synchronized display.

ALT TRIG Switch

The **ALT TRIG** switch is used to select alternate triggering and alternate display when the **DUAL-trace VERT MODE** is selected (the switch has no effect in the **CH 1**, **CH 2**, or **ADD** modes). In the alternate triggering mode (when dual-trace operation is selected), the trigger source alternates between channel 1 and channel 2 with each sweep. This is convenient for checking amplitudes, waveshape, or waveform period measurements, and even permits simultaneous observation of two

waveforms which are not related in frequency or period. However, this setting is not suitable for phase or timing comparison measurements. For such measurements, both traces must be triggered by the same sync signal.

When the **PULL CHOP** and the **ALT TRIG** switches are both engaged during dual-trace operation, synchronization of the display is not possible because the chopping signal becomes the trigger. Use the **ALT** mode by itself, or select **CH 1** or **CH 2** as the trigger source.

TRIG LEVEL and SLOPE Controls (Refer to Fig. 4)

A sweep trigger is developed when the trigger source signal crosses a preset threshold level. Rotation of the **TRIG LEVEL** control varies the threshold level. In the **+** direction, the triggering threshold shifts to a more positive value, and in the **-** direction, the triggering threshold shifts to a more negative value. When the control is centered, the threshold level is set at the approximate average of the signal used as the triggering source. Rotating the control fully counter-clockwise past the click stop, selects the **FIX** trigger mode. In the **FIX** mode, the trigger point is automatically set at the center of the waveform. Proper adjustment of this control usually synchronizes the display.




Fig. 4. Function of Slope and Level Controls.

The **TRIG LEVEL** control adjusts the start of the sweep to almost any desired point on a waveform. On sine wave signals, the phase at which sweep begins is variable. Note that if the **TRIG LEVEL** control is rotated toward its extreme **+** or **-** setting, no sweep will be developed in the **NORM** trigger mode because the

triggering threshold exceeds the peak amplitude of the sync signal.

When the **TRIG SLOPE** control is set to the (+) position (up), the sweep is developed from the trigger source waveform as it crosses the threshold level in a positive-going direction. When the **TRIG SLOPE** control is set to the (-) position (down), a sweep trigger is developed from the trigger source waveform as it crosses the threshold level in a negative-going direction.

COUPLING Switch

1. Use the **AC** position for viewing most types of waveforms. The trigger signal is capacitively coupled and may be used for all signals from 10 Hz to 40 MHz.
2. Use the **LF** position to eliminate high frequency components for stable triggering of low frequency signals.
3. The **TV** position is primarily for viewing composite video waveforms. A sync separator circuit separates sync pulses from video. Vertical sync pulses are selected as trigger when sweep speeds of 0.1 ms/div and slower are selected (**TV V**) and horizontal sync pulses are selected as trigger when sweep speeds of 50 μ s/div and faster are selected (**TV H**). The **SLOPE** switch should be set according to the type of video signal (i.e., if the video signal has negative sync pulses, the **SLOPE** switch should be set to the (-) position. Additional procedures for observing video waveforms are given later in this section of the manual.
4. The **DC** position should be used when it is desirable to include the triggering effects of the dc component.

TIME/DIV Control

Set the **TIME/DIV** control to display the desired number of cycles of the waveform. If there are too many cycles displayed for good resolution, switch to a faster sweep speed. If only a line is displayed, try a slower sweep speed. When the sweep speed is faster than the waveform being observed, only part of it will be displayed, which may appear as a straight line for a square wave or pulse waveform.

HOLDOFF Control (Refer to Fig. 5)

A "holdoff" period occurs immediately after the completion of each sweep, and is a period during which triggering of the next sweep is inhibited. The normal holdoff period varies with the sweep rate, but is adequate to assure complete retrace and stabilization before the next sweep trigger is permitted. The **HOLDOFF** control allows this period to be extended by a variable amount if desired.

This control is usually set to the **NORM** position (fully counterclockwise) because no additional holdoff period is necessary. The **HOLDOFF** control is useful when a complex series of pulses appear periodically, such as in Fig. 5A. Improper sync may produce a double image as in Fig. 5B. Such a display could be synchronized with the **SWEEP/VAR** control, but this is impractical because time measurements are then uncalibrated. An alternate method of synchronizing the display is with the **HOLDOFF** control. The sweep speed remains the same, but the triggering of the next sweep is "held off" by the duration selected by the **HOLDOFF** control. Turn the **HOLDOFF** control clockwise from the **NORM** position until the sweep starts at the same point of the waveform each time. Maximum setting (turned fully clockwise) is 10 times greater than at the **NORM** setting.




Fig. 5. Use of HOLDOFF control.

SINGLE SWEEP

This mode of display is useful for looking at non-synchronous or one time events.

1. Select either the **AUTO** or **NORM SWEEP MODE**. Apply a signal of approx-

imately the same amplitude and frequency as the signal that is to be observed as the trigger signal and set the trigger level.

2. Press and release the **SINGLE SWEEP MODE** switch (it will return to the disengaged position), make sure that the **READY** LED lights to indicate the reset condition. This LED goes out when the sweep period is completed.
3. The scope is now ready to operate in the **SINGLE** sweep mode of operation. Input of the trigger signal results in one and only one sweep.

NOTE

For dual-trace operation simultaneous observation is not possible using the **ALT** mode. Set the unit to the **CHOP** mode in this case.

X-Y OPERATION

X-Y operation permits the oscilloscope to perform many measurements not possible with conventional sweep operation. The CRT display becomes an electronic graph of two instantaneous voltages. The display may be a direct comparison of the two voltages such as a vectorscope display of video color bar patterns. However, the **X-Y** mode can be used to graph almost any dynamic characteristic if a transducer is used to change the characteristic (frequency, temperature, velocity, etc.) into a voltage. One common application is frequency response measurements, where the Y axis corresponds to signal amplitude and the X axis corresponds to frequency.

1. Set the **TRIG SOURCE** switch to the **CH 1/X-Y** position, the **VERT MODE** switch to the **CH 2/X-Y** position, and the **TIME/DIV** control to the **X-Y** position (fully counterclockwise). In this mode, channel 1 becomes the X axis input and channel 2 becomes the Y axis input.
2. The X and Y positions are now adjusted using the horizontal $\blacktriangleleft$ POS and **CH 2** $\blacktriangleup$ POS controls respectively.
3. Adjust the amount of vertical (Y axis) deflection with the **CH 2 VOLTS/DIV** and **VAR** controls.

4. Adjust the amount of horizontal (X axis) deflection with the **CH 1 VOLTS/DIV** and **VAR** controls.

EXTERNAL HORIZONTAL OPERATION

In the **EXT** Horizontal operating mode, an external signal can be connected to the **EXT TRIG** input to control the oscilloscope sweep.

1. Set the **TRIG SOURCE** switch to the **EXT** position, the **VERT MODE** switch to the desired position (the **EXT** Horizontal mode can be used in single-trace, dual-trace, or add mode), and the **TIME/DIV** control to the **X-Y** position (fully counterclockwise). In this mode, the **EXT TRIG** input becomes the sweep signal.
2. The X and Y positions are now adjusted using the horizontal $\blacktriangleleft$ POS and $\blacktriangleup$ POS controls respectively.
3. Adjust the amount of vertical (Y axis) deflection with the appropriate **VOLTS/DIV** and **VAR** controls (**CH 1** for **CH 1 VERT MODE**, **CH 2** for **CH 2 VERT MODE**, or both **CH 1** and **CH 2** for **DUAL VERT MODE**).
4. The amount of horizontal (X axis) deflection is controlled by the amplitude of the signal applied to the **EXT TRIG** jack.

VIDEO SIGNAL OBSERVATION

Setting the **TRIG COUPLING** switch to the **TV** position permits selection of vertical or horizontal sync pulses for sweep triggering when viewing composite video waveforms.

The **TV V** mode is automatically selected at sweep rates of 0.1 ms/div and slower. Vertical sync pulses are selected as trigger to permit viewing of vertical fields and frames of video. A sweep time of 2 ms/div is appropriate for viewing fields of video and 5 ms/div for complete frames (two interlaced fields) of video.

The **TV H** mode is automatically selected at sweep rates of 50 μ s/div and slower. Horizontal sync pulses are selected as trigger to permit viewing of horizontal lines of video. A sweep time of about 10 μ s/div is appropriate

OPERATING INSTRUCTIONS

for displaying lines of video. The **SWEEP/VAR** control can be set to display the exact number of waveforms desired.

At most points of measurement, a composite video signal is of the (-) polarity, that

is, the sync pulses are negative and the video is positive. In this case, use (-) **SLOPE**. If the waveform is taken at a circuit point where the video waveform is inverted, the sync pulses are positive and the video is negative. In this case, use (+) **SLOPE**.

APPLICATIONS

DC VOLTAGE MEASUREMENTS

(Refer to Fig. 6)

The following technique may be used to measure the instantaneous dc level at any portion of a waveform, or to measure a dc voltage where no waveform is present.

1. Connect the signal to be measured to the input jack and set the **VERT MODE** switch to the channel to be used. Set the **VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. The **SWEEP/VAR** and volts/div **VAR** controls must be set to **CAL**.
2. Press the **AUTO SWEEP MODE** switch and set the **AC-GND-DC** switch to **GND**, which establishes a trace at the zero volt reference. Using the $\blacktriangleup$ **POS** control, adjust the trace to the desired reference level position, making sure not to disturb this setting once made.
3. Set the **AC-GND-DC** switch to **DC** to observe the waveform, including its dc component. If an inappropriate reference level position was selected in step 2 or an inappropriate **VOLTS/DIV** setting was made, the waveform may not be visible at this point (deflected completely off the screen). This is especially true when the dc component is large with respect to the waveform amplitude. If so, reset the **VOLTS/DIV** control and repeat steps 2 and 3 until the waveform and the zero reference are both on the screen.
4. Use the $\blacktriangleleft\blacktriangleright$ **POS** control to bring the portion of the waveform to be measured to the center vertical graduation line of the graticule scale.
5. Measure the vertical distance from the zero reference level to the point to be measured (at least 3 divisions desirable for best accuracy). The reference level can be rechecked by momentarily returning the **AC-GND-DC** switch to **GND**.

6. Multiply the distance measured above by the **VOLTS/DIV** setting and the probe attenuation ratio as well. Voltages above the reference level are positive and voltages below the reference level are negative.

The measurement is summarized by the following equation:

$$\text{DC level} = \text{Vert div} \times \text{VOLTS/DIV} \times \text{Probe}$$

For the example shown in Fig. 6, the point being measured is 3.8 divisions from the reference level (ground potential). If the **VOLTS/DIV** control is set to 0.2 V and a 10:1 probe is used, the dc voltage level is calculated as follows:

$$\begin{aligned}\text{DC level} &= 3.8 (\text{div}) \times 0.2 (\text{V/div}) \times 10 \\ &= 7.6 \text{ V}\end{aligned}$$




Fig. 6. DC Voltage Measurement.

MEASUREMENTS OF VOLTAGE BETWEEN TWO POINTS ON A WAVEFORM

(Refer to Fig. 7)

This procedure may be used to measure peak-to-peak voltages, or for measuring the

APPLICATIONS

voltage difference between any two points on a waveform.

1. Connect the signal to be measured to the input connector, set the **VERT MODE** switch to the channel to be used, and set the **AC-GND-DC** switch to **AC**. Set the **VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. The volts/div **VAR** control must be set to **CAL**.
2. Using the $\blacktriangleup$ **POS** control, adjust the waveform position such that one of the two points falls on a major horizontal graduation line.
3. Using the $\blacktriangleleft\blacktriangleright$ **POS** control, adjust the second point to coincide with the center vertical graduation line.
4. Measure the vertical distance between the two points (at least 3 divisions desirable for best accuracy). Multiply the number of divisions by the setting of the **VOLTS/DIV** control. If a probe is used, further multiply this by the probe attenuation ratio.




Fig. 7. Voltage Measurement.

The measurement is summarized by the following equation:

$$\text{Voltage} = \text{Vert div} \times \text{VOLTS/DIV} \times \text{probe}$$

For the example shown in Fig. 7, the two points are separated by 4.4 divisions vertically. If the **VOLTS/DIV** setting is 20 mV and a 10:1 probe is used, the voltage is calculated as follows:

$$\begin{aligned}\text{Voltage} &= 4.4 (\text{div}) \times 20 (\text{mV/div}) \times 10 \\ &= 880 \text{ mV}\end{aligned}$$

ADD MODE APPLICATIONS

Differential Measurements

(Refer to Figs. 8 and 9)

The **ADD** mode can be conveniently used to measure a signal with a reference point other than earth ground. For example, if you wanted to measure the signal present across R_2 in Fig. 8, you would use the following technique:




Fig. 8. Voltage Measurement with Reference Other than Earth Ground.

1. Connect channel 2 to the desired reference point and connect channel 1 to the desired point of measurement.
2. Select the subtract mode of operation by setting the **VERT MODE** switch to the **ADD** position and pulling out the **PULL/INV** switch.
3. Adjust the **CH 1** and **CH 2 VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. The **VAR** controls must both be set

to **CAL** to make voltage measurements. Also, make sure that both attenuator controls are set to the same **VOLTS/DIV** settings.

4. Using the ch 1 or ch 2 $\blacktriangleleft$ **POS**ition control, adjust the waveform position such that one of two points fall on a major horizontal graduation line.
5. Using the $\blacktriangleright$ **POS**ition, adjust the second point to coincide with the center vertical graduation line.
6. Measure the vertical distance between the two points (at least 3 divisions desirable for best accuracy). Multiply the number of divisions by the setting of either **VOLTS/DIV** control. If probes are used, further multiply this by the attenuation ratio of either probe (make sure that both probes are of the same attenuation ratio).

The measurement is summarized by the following equation:

$$\text{Voltage} = \text{Vert div} \times \text{VOLTS/DIV} \times \text{probe}$$




Fig. 9. Differential Voltage Measurement.

For the example shown in Fig. 9, the two points are separated by 4.5 divisions vertically. If the **VOLTS/DIV** setting is 0.1 V and a 10:1 probe is used, the voltage is calculated as follows:

$$\begin{aligned} \text{Voltage} &= 4.5 (\text{div}) \times 0.1 (\text{V/div}) \times 10 \\ &= 4.5 \text{ V} \end{aligned}$$




Fig. 10. Eliminating An Undesired Signal Component.

Elimination of an Undesired Signal Component

(Refer to Fig. 10)

Another application of the **ADD** mode is to cancel out the effect of an undesired signal component which is superimposed on the signal you wish to observe (for example, undesired 60 Hz hum superimposed on an rf signal).

1. Apply the signal containing an undesired component to the **CH 1 (X)** input jack and the undesired signal itself alone to the **CH 2 (Y)** input jack.
2. Select the **DUAL**-trace mode, pull out the **PULL CHOP** switch, and set the

APPLICATIONS

voltage difference between any two points on a waveform.

1. Connect the signal to be measured to the input connector, set the **VERT MODE** switch to the channel to be used, and set the **AC-GND-DC** switch to **AC**. Set the **VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. The volts/div **VAR** control must be set to **CAL**.
2. Using the $\updownarrow$ **POS** control, adjust the waveform position such that one of the two points falls on a major horizontal graduation line.
3. Using the $\blacktriangleleft\blacktriangleright$ **POS** control, adjust the second point to coincide with the center vertical graduation line.
4. Measure the vertical distance between the two points (at least 3 divisions desirable for best accuracy). Multiply the number of divisions by the setting of the **VOLTS/DIV** control. If a probe is used, further multiply this by the probe attenuation ratio.




Fig. 7. Voltage Measurement.

The measurement is summarized by the following equation:

$$\text{Voltage} = \text{Vert div} \times \text{VOLTS/DIV} \times \text{probe}$$

For the example shown in Fig. 7, the two points are separated by 4.4 divisions vertically. If the **VOLTS/DIV** setting is 20 mV and a 10:1 probe is used, the voltage is calculated as follows:

$$\begin{aligned}\text{Voltage} &= 4.4 (\text{div}) \times 20 (\text{mV/div}) \times 10 \\ &= 880 \text{ mV}\end{aligned}$$

ADD MODE APPLICATIONS

Differential Measurements

(Refer to Figs. 8 and 9)

The **ADD** mode can be conveniently used to measure a signal with a reference point other than earth ground. For example, if you wanted to measure the signal present across R_2 in Fig. 8, you would use the following technique:




Fig. 8. Voltage Measurement with Reference Other than Earth Ground.

1. Connect channel 2 to the desired reference point and connect channel 1 to the desired point of measurement.
2. Select the subtract mode of operation by setting the **VERT MODE** switch to the **ADD** position and pulling out the **PULL/INV** switch.
3. Adjust the **CH 1** and **CH 2 VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. The **VAR** controls must both be set

TRIG SOURCE switch to **CH 2**. Adjust the controls to display two signals, such as shown in Fig. 10. Verify that the channel 2 trace represents the unwanted signal in reverse polarity. The polarity may be reversed by engaging the **PULL INV** switch.

- Now set the **VERT MODE** switch to **ADD** and push in the **PULL CHOP** control. Adjust the **CH 2 VOLTS/DIV** and **VAR** controls so that the undesired signal component is cancelled as much as possible. The remaining signal should be the signal you wish to observe alone, free of the unwanted signal.

Push-Pull Amplifier Measurements

The oscilloscope's **ADD** mode can also be conveniently used to make signal measurements and check for proper balance at the outputs of push-pull amplifiers.

- Connect one channel to one amplifier output and the other channel to the other amplifier output.
- Select the subtract mode of operation by setting the **VERT MODE** switch to the **ADD** position and pulling the **PULL INV** switch.

NOTE

Because the two outputs of a push-pull amplifier are out of phase they tend to subtract. It is necessary to invert the channel 2 input to cause the signals to add.

- Adjust the **CH 1** and **CH 2 VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. The **VAR** controls must both be set to **CAL** to make voltage measurements. Also, make sure that both attenuator controls are set to the same **VOLTS/DIV** settings.
- Make peak-to-peak signal measurements by performing steps 4 through 6 of "Differential Voltage Measurements".
- To check amplifier balance, press the **PULL INV** switch and observe the dis-

play. If the amplifier is perfectly balanced, the two outputs should fully cancel each other. The resulting displayed waveform should be a flat trace. Any displayed signal equals the imbalance.

TIME MEASUREMENTS

(Refer to Fig. 11)

This is the procedure for making time (period) measurements between two points on a waveform. The two points may be the beginning and ending of one complete cycle if desired.

- Connect the signal to be measured to the input connector and set the **VERT MODE** switch to the channel to be used. Set the **VOLTS/DIV** and **TIME/DIV** controls to obtain a normal display of the waveform to be measured. Be sure the **SWEEP/VAR** control is set to **CAL**.
- Using the $\blacktriangle$ **POS** control, set one of the points to be used as a reference to coincide with the horizontal center line. Use the $\blacktriangleleft$ **POS** control to set this point at the intersection of any vertical graduation line.
- Measure the horizontal distance between the two points (at least 4 divisions desirable for best accuracy). Multiply this by the setting of the **TIME/DIV** control to obtain the time between the two points. If **X10 MAG** is used, multiply this further by 1/10.

The measurement is summarized by the following equation:

$$\text{Time} = \text{Hor div} \times \text{TIME/DIV}$$

(x 1/10 if **X10 MAG** is used)

For the example shown in Fig. 11, the horizontal distance between the two points is 5.4 divisions. If the **TIME/DIV** setting is 0.2 ms and **X10 MAG** is not used, the time period is calculated as follows:

$$\begin{aligned} \text{Time} &= 5.4 (\text{div}) \times 0.2 (\text{ms/div}) \\ &= 1.08 \text{ ms} \end{aligned}$$




Fig. 11. Time Measurement.




Fig. 12. Frequency Measurement.

FREQUENCY MEASUREMENTS

Method No. 1

(Refer to Fig. 12)

Frequency measurements are made by measuring the time period of one cycle of waveform and calculating the frequency, which equals the reciprocal of the time period.

1. Set up the oscilloscope to display one cycle of waveform (see Fig. 12).
2. Measure the time period of one cycle and calculate the frequency as follows:

$$\text{Freq} = \frac{1}{\text{Period}}$$

In the example shown in Fig. 12, a period of 40 μs is observed. Substituting this value into the above equation, the frequency is calculated as follows:

$$\begin{aligned}\text{Freq} &= \frac{1}{40 \times 10^{-6}} \\ &= 2.5 \times 10^4 \\ &= 25 \text{ kHz}\end{aligned}$$

Method No. 2

(Refer to Fig. 13)

While the previously described method relies upon direct period measurement of one cycle, the frequency may also be measured by counting the number of cycles present in a given time period.

1. Set up the oscilloscope to display several cycles of the waveform. The **SWEEP/VAR** control must be set to **CAL**.
2. Count the number of cycles of waveform between a chosen set of vertical graduation lines (see Fig. 13).
3. Multiply the number of horizontal divisions by the **TIME/DIV** setting to calculate the time span. Multiply the reciprocal of this value by the number of cycles present in the time span. If **X10 MAG** is used, multiply this further by 10. Note that errors will occur for displays having only a few cycles.

The measurement is summarized by the following equation:

$$\text{Freq} = \frac{\text{No of cycles (x 10 for X10 MAG)}}{\text{Hor div x TIME/DIV}}$$

For the example shown in Fig. 13, there are 10 cycles within 7 divisions. If the **TIME/DIV** setting is 5 μs and **X10 MAG** is not used, the frequency is calculated as follows:

$$\text{Freq} = \frac{10 \text{ (cycles)}}{7 \text{ (div)} \times 5 \text{ (}\mu\text{s)}} = 285.7 \text{ kHz}$$




Fig. 13. Alternate Method of Frequency Measurement.

PULSE WIDTH MEASUREMENTS

(Refer to Fig. 14)

1. Apply the pulse signal to the input jack and set the **VERT MODE** switch to the channel to be used.
2. Use the **VOLTS/DIV** and volts/div **VAR** controls to adjust the display so the waveform is easily observed. Use the $\blacktriangleup$ **POS** control to position the pulse over the center horizontal graduation line. Use the $\blacktriangleleft$ **POS** control to align the leading edge of the pulse with one of the vertical graduation lines.
3. Measure the distance between the leading edge and trailing edge of the pulse (along the center horizontal graduation line). Be sure that the **SWEEP/VAR** control is set to **CAL**. Multiply the number of horizontal divisions by the **TIME/DIV**, and if **X10 MAG** is used, further multiply this value by 1/10.

The measurement is summarized by the following equation:

$$\text{Pulse Width} = \text{Hor div} \times \text{TIME/DIV}$$

(x 1/10 if **X10 MAG** is used)

For the example shown in Fig. 14, the pulse width at the center of the pulse is 4.6 divisions. If the **TIME/DIV** setting is 0.2 ms and **X10 MAG** is used, the pulse width is calculated as follows:

$$\text{Pulse Width} =$$

$$4.6 \text{ (div)} \times 0.2 \text{ (ms/div)} \times 1/10$$

$$= .092 \text{ ms or } 92 \mu\text{s}$$




Fig. 14. Pulse Width Measurement.

PULSE RISE TIME AND FALL TIME MEASUREMENTS

Method No. 1:

(Refer to Fig. 15)

For rise time and fall time measurements, the 10% and 90% amplitude points are used as starting and ending reference points.

1. Apply a signal to the input jack and set the **VERT MODE** switch to the channel to be used. Use the **VOLTS/DIV** and volts/div **VAR** controls to adjust the waveform peak to peak height to six divisions.
2. Using the $\blacktriangleup$ **POS** control, adjust the display so that the waveform is centered vertically on the display. Set the **TIME/DIV** control to a setting as fast as possible while still being able to observe the 10% and 90% points. Set the **SWEEP/VAR** control to the **CAL** position.

3. Use the $\blacktriangleleft$ POS control to adjust the 10% point to coincide with a vertical graduation line and measure the horizontal distance in divisions between the 10% and 90% points on the waveform. Multiply this by the TIME/DIV setting and also by 1/10 if the X10 MAG mode was used.

NOTE

Be sure that the correct 10% and 90% lines are used. For such measurements the 0, 10, 90, and 100% points are marked on the CRT screen.

The measurement is summarized by the following equation:

$$\text{Rise Time} = \text{Hor div} \times \text{TIME/DIV}$$

($\times 1/10$ if X10 MAG is used)

For the example shown in Fig. 15, the horizontal distance is 4.0 divisions. The TIME/DIV setting is 2 μs . The rise time is calculated as follows:

$$\text{Rise Time} = 4.0 (\text{div}) \times 2 (\mu\text{s}/\text{div}) = 8 \mu\text{s}$$




Fig. 15. Rise Time and Fall Time Measurement.

Method No. 2:

(Refer to Fig. 16)

The following step can be substituted for step 3 in method No. 1:

Use the $\blacktriangleleft$ POS control to set the 10% point to coincide with the center vertical

graduation line and measure the horizontal distance to the point of the intersection of the waveform with the center horizontal line. Let this distance be D_1 . Next, adjust the waveform position so that the 90% point coincides with the vertical centerline and measure the distance from that line to the intersection of the waveform with the horizontal centerline. Let this distance be D_2 . The total horizontal distance is D_1 plus D_2 .

The following equation summarizes the measurement:

$$\text{Rise Time} = (D_1 + D_2) \times \text{TIME/DIV}$$

($\times 1/10$ if X10 MAG is used)

For the example shown in Fig. 16, D_1 is 1.8 divisions and D_2 is 2.2 divisions. If the TIME/DIV setting is 2 μs , the rise time is calculated as follows:

$$\text{Rise Time} = (1.8 + 2.2) \times 2 (\mu\text{s}/\text{div}) = 8 \mu\text{s}$$

NOTE

See APPENDIX I for important rise and fall time considerations.




Fig. 16. Rise Time and Fall Time Measurement.

TIME DIFFERENCE MEASUREMENTS

(Refer to Fig. 17)

This procedure is useful in measurement of time difference between signals that are synchronized to one another but skewed in time.

APPLICATIONS

1. Apply the two signals to the **CH 1 (X)** and **CH 2 (Y)** input jacks and select the dual-trace display mode.
2. Select the faster of the two signals as the **TRIG SOURCE** and use the **VOLTS/DIV** and **TIME/DIV** controls to obtain an easily observed display.
3. Use the $\blacktriangle$ **POS** controls to superimpose both waveforms to intersect the center horizontal graduation line as shown in Fig. 17. Use the $\blacktriangleleft$ **POS** control to set the reference signal coincident with one of the vertical graduation lines.
4. Measure the horizontal distance between the two signals and multiply this distance (in divisions) by the **TIME/DIV** setting. If **X10 MAG** is used, multiply this again by 1/10.




Fig. 17. Time Difference Measurement.

The measurement is summarized by the following equation:

$$\text{Time} = \text{Hor div} \times \text{TIME/DIV}$$

(x 1/10 if **X10 MAG** is used)

For the example shown in Fig. 17, the horizontal distance measured is 4.4 divisions. If the **TIME/DIV** is 0.2 ms and **X10 MAG** is not used, the time difference is calculated as follows:

$$\text{Time} = 4.4 (\text{div}) \times 0.2 (\text{ms/div})$$

$$= 0.88 \text{ ms or } 880 \mu\text{s}$$

PHASE DIFFERENCE MEASUREMENTS

Method No. 1

(Refer to Fig. 18)

This procedure is useful in measuring the phase difference of signals of the same frequency.

1. Apply the two signals to the **CH 1 (X)** and **CH 2 (Y)** input jacks, selecting the dual-trace display mode.
2. Set the **TRIG SOURCE** switch to the signal which is leading in phase and use the **VOLTS/DIV** controls to adjust the two waveforms so they are equal in amplitude.
3. Use the $\blacktriangle$ **POS** controls to position the waveforms in the vertical center of the screen. Use the **TIME/DIV** and **SWEEP/VAR** controls to adjust the display so one cycle of the reference signal occupies 8 divisions horizontally (see Fig. 18). The trigger **LEVEL** and $\blacktriangleleft$ **POS** controls are also useful in achieving this display. The display should be as shown in Fig. 18, where one division now represents 45° in phase.




Fig. 18. Phase Difference Measurement.

4. Measure the horizontal distance between corresponding points on the two waveforms. Multiply the distance (in divisions) times 45° per division to obtain the phase difference.

The measurement is summarized by the following equation:

$$\text{Phase difference} = \text{Hor div} \times 45^\circ/\text{div}$$

For the example shown in Fig. 18, the horizontal distance is 1.7 divisions. Thus, the phase difference is calculated as follows:

$$\text{Phase difference} = 1.7 \times 45^\circ/\text{div} = 76.5^\circ$$

Method No. 2

(Refer to Fig. 19)

The above procedure allows 45° per division, which may not give the desired accuracy for small phase differences.




Fig. 19. Measuring Small Phase Difference.

If greater accuracy is required, the **TIME/DIV** setting may be changed to expand the display

as shown in Fig. 19, but the **SWEEP/VAR** setting must not be touched. If necessary, the **TRIG LEVEL** control may be readjusted. For this type of operation, the relationship of one division to 45° no longer holds. Instead the following equation must be used:

$$\text{Phase diff} = \text{Hor div} \times 45^\circ/\text{div} \times \frac{A}{B}$$

Where:

A = New **TIME/DIV** setting.

B = Original **TIME/DIV** setting.

A simpler method of obtaining more accuracy quickly is to simply use **X10 MAG** for a scale factor of $4.5^\circ/\text{division}$.

RELATIVE MEASUREMENTS

If the amplitude and period of some reference signal are known, an unknown signal may be measured for amplitude and period without the volts/div and **SWEEP/VAR** controls set to **CAL**. The measurement is made in units relative to the reference signal.

Relative Voltage Measurements

(Refer to Fig. 20)

1. Apply the reference signal to the input jack and adjust the display for a normal waveform display. Adjust the **VOLTS/DIV**, volts/div **VAR**, and **SWEEP/VAR** controls so that the amplitude of the reference signal occupies a fixed number of divisions. After adjusting, be sure not to disturb the setting of the volts/div **VAR** control.
2. Calculate the vertical calibration coefficient as follows:

$$\text{vertical coefficient} = \frac{C}{D \times E}$$

Where:

C = Amplitude of reference signal (in volts).

D = Amplitude of reference signal (in divisions).

E = **VOLTS/DIV** setting.

APPLICATIONS

3. Remove the reference signal and apply the unknown signal to the input jack, using only the **VOLTS/DIV** control to adjust the amplitude for easy observation (do not disturb the volts/div **VAR** setting).
4. Measure the amplitude of the displayed waveform, in divisions. Multiply the number of divisions by the **VOLTS/DIV** setting and the vertical coefficient from above to find the value of the unknown voltage.

The measurement is summarized by the following equation:

$$\text{Unknown Voltage} = \text{Vert div} \times \text{VOLTS/DIV} \times \text{vert coefficient}$$

For the example shown in Fig. 20, the **VAR** control is adjusted so the amplitude of the reference signal is 4 divisions. If the reference signal is 2.0 V p-p, and the **VOLTS/DIV** setting is 1 V, the vertical coefficient is 0.5; which was calculated as follows:

$$\begin{aligned} \text{vertical coefficient} &= \frac{2 \text{ (V)}}{4 \text{ (div)} \times 1 \text{ (V/div)}} \\ &= 0.5 \end{aligned}$$

For the example shown in Fig. 20, the amplitude of the unknown signal is 3 divisions, and the previously calculated vertical coefficient is 0.5. If the **VOLTS/DIV** setting is 5 V, the unknown signal is 7.5 V p-p; which was calculated as follows:

$$\begin{aligned} \text{Unknown Voltage} &= \\ 3 \text{ (div)} \times 5 \text{ (V/div)} \times 0.5 \text{ (vert coef)} \\ &= 7.5 \text{ V} \end{aligned}$$

NOTE

It is preferable that the reference voltage be the peak-to-peak value, as in the previous example. The measurement holds true for all waveforms if a p-p reference is used. It is also possi-

ble to use an rms value for the reference voltage. The unknown voltage value will also be in rms, but the measurement holds true only if both the reference and unknown signals are undistorted sine waves.




Fig. 20. Voltage Measurement, Relative Method.

Relative Period Measurements (Refer to Fig. 21)

1. Apply the reference signal to the input jack and adjust the display for a normal waveform display. Using the **TIME/DIV** and **SWEEP/VAR** controls, adjust one cycle of the reference signal to occupy a fixed number of horizontal divisions. After this is done, be sure not to disturb the **SWEEP/VAR** control setting.
2. Calculate the sweep (horizontal) calibration coefficient using the following equation:

$$\text{Sweep coefficient} = \frac{F}{G \times H}$$

Where:

F = Period of reference signal (seconds).

G = Horizontal width of reference signal (divisions).

H = TIME/DIV setting.

3. Remove the reference signal and apply the unknown signal to the input jack, using only the TIME/DIV control to adjust the width of the display (do not disturb the SWEEP/VAR setting).
4. Measure the width of one cycle of the displayed waveform, in divisions. Multiply the number of divisions by the TIME/DIV setting and the sweep coefficient from above to find the period of the unknown waveform.

The measurement is summarized by the following equation:

$$\text{Unknown Period} = \text{Horizontal divisions} \times$$

$$\text{TIME/DIV} \times \text{sweep coefficient}$$

For the example in Fig. 21A, the SWEEP/VAR control is adjusted so the reference signal occupies 5 horizontal divisions. If the reference signal is 1.75 kHz, and the TIME/DIV control is 0.1 ms, the sweep coefficient is calculated as follows:

$$\begin{aligned} \text{sweep coefficient} &= \frac{1.75 \text{ kHz}^{-1}}{5 (\text{div}) \times 0.1 (\text{ms/div})} \\ &= 1.143 \end{aligned}$$

For the example in Fig. 21B, the width of the unknown signal is 7 divisions, and the previously calculated sweep coefficient is 1.143. If the TIME/DIV setting is 0.2 ms, the period is calculated as follows:

$$\text{Unknown Period} =$$

$$\begin{aligned} &7 (\text{div}) \times 0.2 (\text{ms/div}) \times 1.143 (\text{sweep coef}) \\ &= 1.6 \text{ ms} \end{aligned}$$




Fig. 21. Period Measurement, Relative Method.


X-Y MODE APPLICATIONS

Phase Measurements

(Refer to Fig. 22)

A dual-trace method of phase measurement was previously described. A second method of phase measurement requires calculations based on the Lissajous patterns obtained using X-Y operation. Distortion due to non-linear amplification can also be displayed.

A sine wave is applied to the audio circuit being tested. The same sine wave is also applied to the vertical input of the oscilloscope, and the output of the tested circuit is applied to the horizontal input of the oscilloscope. The amount of phase difference between the two signals can be calculated from the resulting waveform.



APPLICATIONS

1. Using an audio generator with a pure sinusoidal signal, apply a sine wave test signal at the desired test frequency to the audio network being tested.
2. Set the signal generator output for the normal operating level of the circuit being tested. If desired, the circuit's output may first be observed on the oscilloscope with normal sweep operation. If the test circuit is overdriven, the sine wave display on the oscilloscope is clipped and the signal level must be reduced.
3. Connect channel 1 to the input and channel 2 to the output of the test circuit. Set channel 1 and 2 gain controls for exactly the same amplitude waveform on the display in normal sweep operation.
4. Select X-Y operation by setting the **TIME/DIV** control fully counterclockwise (X-Y), the **TRIG SOURCE** switch to the **CH 1/X-Y** position, and the **VERT MODE** switch to the **CH 2/X-Y** position.




Fig. 22. Typical X-Y Phase Measurement Displays.

5. If necessary, repeat step 3, readjusting the channel 1 and 2 gain controls for a suitable viewing size. Some typical results are shown in Fig. 22.

If the two signals are in phase, the oscilloscope trace is a straight diagonal line. If the vertical and horizontal gain are properly adjusted, this line is at a 45° angle. A 90° phase

shift produces a circular oscilloscope pattern. Phase shift of less (or more) than 90° produces an elliptical oscilloscope pattern. The amount of phase shift can be calculated from the oscilloscope trace as shown in Fig. 23.




Fig. 23. Phase Measurement, X-Y Operation.

Frequency Response Measurements (Refer to Fig. 24)

A sweep generator and the X-Y mode of this oscilloscope may be used to measure the audio or rf frequency response of an active or passive device up to 40 MHz, such as an amplifier, band pass filter, coupling network, etc.




Fig. 24. Frequency Response Measurement.

1. Connect the audio or rf output of the sweep generator to the input of the circuit under test and the output of the test circuit to channel 1 (vertical axis) of the oscilloscope. A demodulator probe will give a "text book" frequency response display as shown in Fig. 24, but a stand-

ard probe can be used which will result in an envelope display.

2. Connect the sweep ramp voltage of the sweep generator to the channel 2 input of the oscilloscope.
3. Set the **TIME/DIV** control to the **X-Y** position (fully counterclockwise), the **TRIG SOURCE** switch to the **CH 1/X-Y** position, the **VERT MODE** switch to the **CH 2/X-Y** position, and adjust the channel 1 and 2 controls for a suitable viewing size.

EXTERNAL HORIZONTAL SWEEP APPLICATIONS

(Refer to Fig. 25 and 26)

The **EXT** Horizontal operating mode allows the Model 1541A oscilloscope to be used to view a frequency response sweep envelope. Unlike oscilloscopes which have no external sweep input, a frequency response sweep envelope can be synchronized, allowing for a synchronized, usable frequency response display. Typical frequency response envelopes can be viewed as follows (Refer to Fig. 25 for set-up):




Fig. 25. Frequency Response Set-Up.

1. Set the **TIME/DIV** control on the oscilloscope to the **X-Y** position (fully counterclockwise), the **TRIG SOURCE** switch to the **EXT** position, and the **VERT MODE** switch to the **CH 1** position.
2. Connect a sweep/function generator to the input of the equipment to be tested.
3. Connect the output of the equipment under test to the **CH 1 (X)** input on the oscilloscope.
4. Connect the sweep ramp output of the sweep/function generator to the **EXT TRIG** input on the oscilloscope.
5. Set the sweep/function generator up for the fastest sweep possible (a faster sweep causes the oscilloscope display to "flicker" less) and set the desired start and stop sweep points.
6. Adjust the **CH 1 VOLTS/DIV** control to obtain about five or six vertical divisions of signal at it's highest amplitude.
7. The oscilloscope display should now show a frequency response envelope. The response in Fig. 26 is that of a circuit that has attenuation at lower frequencies.




Fig. 26. Frequency Response Envelope.

MAINTENANCE

WARNING

The following instructions are for use by qualified service personnel only. To avoid electrical shock, do not perform any servicing other than contained in the operating instructions unless you are qualified to do so.

High voltage up to 12,000 volts is present when covers are removed and the unit is operating. Remember that high voltage may be retained indefinitely on high voltage capacitors. Also remember that ac line voltage is present on line voltage input circuits any time the instrument is plugged into an ac outlet, even if turned off. Unplug the oscilloscope and discharge high voltage capacitors before performing service procedures.

FUSE REPLACEMENT

If the fuse blows, the pilot light will go out and the oscilloscope will not operate. The fuse should not normally open unless a problem has developed in the unit. Try to determine and correct the cause of the blown fuse, then replace only with the correct value fuse. For 100 V or 120 V operation, use a 0.5 A, 250 V, 3 AG, slow-blow fuse (Dynascan part number 190-251-3-102). For 220 V, 230 V, or 240 V operation, use a 0.3 A, 250 V, 3 AG, slow-blow fuse (Dynascan part number 190-004-9-001). The fuse is located on the rear panel (see Fig. 2).

CASE REMOVAL

To remove the case from the Model 1541A oscilloscope, perform the following steps:

1. Unplug the line cord.
2. Remove the nine screws that secure the top case to the chassis (three along each

bottom edge of the top case and three at the back of the top case).

3. Slide the case top back and lift up.
4. To reinstall the case, reverse the procedure.

LINE VOLTAGE SELECTION

The Model 1541A oscilloscope is designed to work with a wide variety of line voltages. These voltages include, 110 V, 120 V, 220 V, 230 V, and 240 V at either 50 or 60 Hz. To select the desired line voltage, perform the following steps:

WARNING

Make sure the oscilloscope is unplugged before converting line voltage.

1. Remove the case by following the instructions in the previous paragraph titled "CASE REMOVAL".
2. Locate the line voltage printed circuit board at the back of the oscilloscope.
3. Carefully unplug the 5-pin socket (the largest of the three sockets plugged into the circuit board).
4. Connect the five pin socket to the pin header for the desired line voltage. The voltage range for each of the 5-pin headers is as follows:

110 V - 99 V to 121 V
120 V - 108 V to 132 V
220 V - 198 V to 242 V
230 V - 207 V to 253 V
240 V - 216 V to 264 V

5. Be sure to use the proper fuse for the line voltage selected (see the **FUSE REPLACEMENT** paragraph located previ-

ously in this section of the instruction manual). Also, be sure to change fuse information label if fuse value is changed

PERIODIC ADJUSTMENTS

Screwdriver adjustments only need to be checked and adjusted periodically. Probe compensation, and trace rotation are included in this category. Procedures are given below.

Probe Compensation

1. Connect probes to **CH 1 (X)** and **CH 2 (Y)** INPUT jacks. Repeat procedure for each probe.
2. Touch tip of probe to **CAL** terminal.
3. Adjust oscilloscope controls to display 3 or 4 cycles of **CAL** square wave at 5 or 6 divisions amplitude.
4. Adjust compensation trimmer on probe for optimum square wave (minimum overshoot, rounding off, and tilt). Refer to Fig. 27.




Fig. 27. Probe Compensation Adjustment.

Trace Rotation Adjustment

1. Set oscilloscope controls for a single trace display in **CH 1** mode, and with the

channel 1 **AC-GND-DC** switch set to **GND**.

2. Use the channel 1 **POS** control to position the trace over the center horizontal line on the graticule scale. The trace should be exactly parallel with the horizontal line.
3. Use the **TRACE ROTATION** adjustment on the front panel to eliminate any trace tilt.

CALIBRATION CHECK

A general check of calibration accuracy may be made by displaying the output of the **CAL** terminal on the screen. This terminal provides a square wave of 2.0 V p-p. This signal should produce a displayed waveform amplitude of four divisions at 0.5 V/div sensitivity for both channel 1 and 2 (with probes set for direct). With probes set for 10:1, there should be four divisions amplitude at 50 mV/div sensitivity. The volts/div and **SWEEP/VAR** controls must be set to **CAL** during this check.

The **CAL** signal may be used only as a general check of calibration accuracy, not as a signal source for performing recalibration adjustments; a signal source of $\pm 0.3\%$ or better accuracy is required for calibration adjustments.

INSTRUMENT REPAIR SERVICE

Because of the specialized skills and test equipment required for instrument repair and calibration, many customers prefer to rely upon **B & K-Precision** for this service. We maintain a network of **B & K-Precision** authorized service agencies for this purpose. To use this service, even if the oscilloscope is no longer under warranty, follow the instructions given in the **WARRANTY SERVICE INSTRUCTION** portion of this manual. There is a nominal charge for instruments out of warranty.

APPENDIX I

IMPORTANT CONSIDERATIONS FOR RISE TIME AND FALL TIME MEASUREMENTS

Error In Observed Measurement

The observed rise time (or fall time) as seen on the CRT is actually the cascaded rise time of the pulse being measured and the oscilloscope's own risetime. The two rise times are combined in square law addition as follows:

$$T_{\text{observed}} = \sqrt{(T_{\text{pulse}})^2 + (T_{\text{scope}})^2}$$

The effect of the oscilloscope's rise time is almost negligible when its rise time is at least 3 times as fast as that of the pulse being measured. Thus, slower rise times may be measured directly from the CRT. However, for faster rise time pulses, an error is introduced that increases progressively as the pulse rise time approaches that of the oscilloscope. Accurate measurements can still be obtained by calculation as described below.

Direct Measurements

The Model 1541A Oscilloscope has a rated rise time of 8.8 ns at 5 mV/div and higher sensitivity. Thus, pulse rise times of about 27 ns or greater can be measured directly. Most rise times are measured at the fastest sweep speed and using **X10 MAG**. For Model 1541A, this sweep rate is 20 ns/div. A rise time measurement of less than about 2 divisions should be calculated.

With **X5 MAG** selected (1 mV/div and 2 mV/div sensitivity), the rated rise time is increased to 17.5 ns. Pulse rise times must be

at least 60 ns (for direct measurement on these ranges). Because of this, the **X5 MAG** mode of operation should be avoided for rise time measurements if possible.

Calculated Measurements

For observed rise times of less than 27 ns, the pulse rise time should be calculated to eliminate the error introduced by the cascaded oscilloscope rise time. Calculate pulse rise time as follows:

$$T_{\text{pulse}} = \sqrt{(T_{\text{observed}})^2 - (T_{\text{scope}})^2}$$

Limits Of Measurement

Measurements of pulse rise times that are faster than the oscilloscope's rated rise time are not recommended because a very small reading error introduces significant error into the calculation. This limit is reached when the "observed" rise time is about 1.3 times greater than the scope's rated rise time, about 12 ns.

Probe Considerations

For fast rise time measurements which approach the limits of measurement, direct connection via 50 Ω coaxial cable and 50 Ω termination is recommended where possible. When a probe is used, its rise time is also cascaded in square law addition. Thus the probe rating should be considerably faster than the oscilloscope if it is to be disregarded in the measurement.

WARRANTY SERVICE INSTRUCTIONS
(For U.S.A. and its Overseas Territories)

1. Refer to the MAINTENANCE section of your **B & K-Precision** instruction manual for adjustments that may be applicable.
2. If the above-mentioned does not correct the problem you are experiencing with your unit, pack it securely (preferably in the original carton or double-packed). Enclose a letter describing the problem and include your name and address. Deliver to, or ship PREPAID (UPS preferred in U.S.A.) to the nearest **B & K-Precision** authorized service agency (see list enclosed with unit).

If your list of authorized **B & K-Precision** service agencies has been misplaced, contact your distributor for the name of your nearest service agency, or write to:

B & K-Precision, Dynascan Corporation
Factory Service Operations
6460 West Cortland Street
Chicago, Illinois 60635
Tel (312) 889-8870
Telex: 25-3475

Also use this address for technical inquiries
and replacement parts orders.

LIMITED TWO-YEAR WARRANTY

DYNASCAN CORPORATION warrants to the original purchaser that its **B & K-Precision** product, and the component parts thereof, will be free from defects in workmanship and materials for a period of two years from the date of purchase.

DYNASCAN will, without charge, repair or replace, at its option, defective product or component parts upon delivery to an authorized **B & K-Precision** service contractor or the factory service department, accompanied by proof of the purchase date in the form of a sales receipt.

To obtain warranty coverage in the U.S.A., this product must be registered by completing and mailing the enclosed warranty registration card to DYNASCAN, **B & K-Precision**, 6460 West Cortland Street, Chicago, Illinois 60635 within fifteen (15) days from the date of purchase.

Exclusions: This warranty does not apply in the event of misuse or abuse of the product or as a result of unauthorized alterations or repairs. It is void if the serial number is altered, defaced or removed.


DYNASCAN shall not be liable for any consequential damages, including without limitation damages resulting from loss of use. Some states do not allow limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you.

This warranty gives you specific rights and you may also have other rights which vary from state to state.

For your convenience we suggest you contact your **B & K-Precision** distributor, who may be authorized to make repairs or can refer you to the nearest service contractor. If warranty service cannot be obtained locally, please send the unit to **B & K-Precision** Service Department, 6460 West Cortland Street, Chicago, Illinois 60635, properly packaged to avoid damage in shipment.

B & K-Precision Test Instruments warrants products sold only in the U.S.A. and its overseas territories. In other countries, each distributor warrants the **B & K-Precision** products which it sells.

NOTES




BK PRECISION
DYNASCAN CORPORATION

6460 W. Cortland St. • Chicago, IL 60635
312-889-8870

© 1987 DYNASCAN CORP.

Printed in U.S.A.

SERVICING INFORMATION



BK PRECISION®

MODEL 1541A

40 MHz DUAL-TRACE OSCILLOSCOPE

PARTS LIST

SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.	SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.
---------------------	-------------	-----------------------------	---------------------	-------------	-----------------------------

FINAL ASSY

ELECTRICAL

1/2 Amp, 250V, 3AG Slow Blow Fuse (100 V, 120 V)	190-251-3-102
0.3 Amp, 250V, 3AG Slow Blow Fuse (220 V, 230 V, 240 V)	190-004-9-001
Power Transformer	065-233-9-001
10 kΩ Potentiometer w/switch (VARIABLE, PULL 10 MAG)	008-881-9-003
10 kΩ Potentiometer (POSITION)	008-881-9-002
150BYB31 CRT	230-039-9-001
BNC Connector	772-024-9-001
CRT Socket PC Board	303-136-9-001
Cable Assembly (J34 to CAL)	428-182-9-001
Cable Assembly (J5A to J5B)	428-182-9-002
Cable Assembly (J15A to J15B)	428-182-9-003
Cable Assembly (J32 to Z Axis INPUT)	428-182-9-004
Cable Assembly (J1 to CH 1 OUTPUT)	428-182-9-005
Cable Assembly (J13A to J13B and J25A to J25B)	428-182-9-006
Cable Assembly (J9A to J9B)	428-182-9-007
Cable Assembly (J21A to J21B)	428-182-9-008
Cable Assembly (CRT to GND)	428-182-9-009
Cable Assembly (Ground)	428-182-9-010
Cable Assembly (J16 to POS.)	428-182-9-011
Cable Assembly (J10 to EXT.)	428-182-9-012
Cable Assembly (J18 to CRT)	428-182-9-013
Cable Assembly (J19 to CRT)	428-182-9-014
Cable Assembly, Twin Lead (J6 to CRT and J7 to CRT)	428-182-9-015
Cable Assembly (J31 to CRT)	428-182-9-016
Cable Assembly (J30 to CRT)	428-182-9-017
Cable Assembly (J11A to J11B)	428-182-9-020
Cable Assembly (J2A to J2B and J4A to J4B)	428-182-9-021
Cable Assembly (J12A to J12B)	428-182-9-022
Cable Assembly (J28A to J28B)	428-182-9-023
Line Cord, 3 Wire CSA	420-013-9-001
Trace Rotation Coil	040-008-9-001
Wire Assembly (J14 to VAR.)	428-182-9-018
Wire Assembly (J17 to X10 MAG Switch)	428-182-9-019
Wire Assembly (J26A to J26B)	428-182-0-024
Wire Assembly (J8A to J8B)	428-182-9-025
Wire Assembly (J27A to J27B)	428-182-9-026
Wire Assembly (J3A to J3B)	428-182-9-027

MECHANICAL

Lamp Holder, Plastic	380-593-9-005
AC Cord Wrap/Rear Foot	380-594-9-001
CAL Terminal, Axis	777-086-9-001
CAL Terminal, Washer	777-086-9-002
CAL Terminal, Nut	777-086-9-003
CAL Terminal, Bakelite Pipe	777-086-9-004
CAL Terminal, Bakelite Axis	777-086-9-005
CRT Bracket, Bottom	250-269-9-001
CRT Bracket (Cross Brace)	254-127-9-006

CRT Bracket, Top	250-269-9-002
CRT Clip, Copper	741-206-9-002
CRT Filter, Blue	380-593-9-001
CRT Shield	256-274-9-001
CRT Socket, 14 Pin	749-121-9-001
CRT Socket Cover, Plastic	380-593-9-004
Bottom Cover	252-065-9-001
Bracket, Side	254-127-9-008
Bracket (Small "Z" Shaped)	250-269-9-003
Cable Tie	380-593-9-003
Cover, Handle (Chrome)	746-076-9-003
Clamp, Tilt Stand	741-206-9-001
Dust Cover (AC/GND/DC Switch)	769-192-9-001
Dust Cover (VERT MODE Switch)	769-192-9-002
Dust Cover (SLOPE/COUPLING SOURCE Switch)	769-192-9-003
Frame, Bottom Center	254-127-9-007
Frame, Bottom Left	254-127-9-003
Frame, Bottom Right	254-127-9-002
Frame, Upper Center	254-127-9-004
Frame, Upper Right	254-127-9-005
Front Panel Bezel	380-595-9-001
Front Panel Inlay	260-489-9-001
Front Sub-Panel	254-127-9-001
Fuse Holder	742-052-9-001
Fuse Label, 1/2 A	483-699-9-003
Ground Terminal	740-053-9-001
Handle (Outer)	746-076-9-001
High Voltage Shield Cover, Lower	256-274-9-002
High Voltage Shield Plate	256-274-9-004
Instruction Manual	480-585-9-001
Knob, Gray, 16mm	751-312-9-001
Knob, Gray w/Set Screw, 16mm (HOLD OFF)	751-340-9-001
Knob, Dark Gray, w/Set Screw, 9.5mm (VOLT/DIV VAR.)	751-340-9-002
Knob, Gray, w/Set Screw, 18mm (VOLTS/DIV)	751-340-9-003
Knob, Gray, w/Set Screw, 23mm (TIME/DIV)	751-340-9-004
Knob, Dark Gray, 13mm (LEVEL)	751-341-9-001
Label "CAUTION HIGH VOLTAGE"	483-699-9-001
Lever Switch Knob, Gray	384-115-9-001
Metal Insert, 3mm Thread (Front Panel)	758-046-9-001
Nameplate LOGO, Front	260-488-9-001
Pushbutton Switch Bezel	380-596-9-001
Rear Panel	262-073-9-001
Rubber Foot	381-152-9-001
Rubber Pad (CRT Bracket)	381-178-9-001
Rubber Pad 18 x 15mm (CRT Bezel)	381-178-9-002
Rubber Pad 35 x 15mm (CRT Bezel)	381-178-9-003
Rubber Pad (Under CRT Shield)	381-178-9-004
Set Screw, 3 x 3mm x 0.5P (Knobs)	633-010-9-001



DIVISION OF PIONEER-STANDARD ELECTRONICS, INC.

1008 CASTLEPLACE DRIVE / INDIANAPOLIS, IN 46250 (317) 849-7300

TOLL FREE 800-382-6503 KY 800-428-9128

COMPOSITE
499-374-9-001

ALPHANUMERIC ID	DESCRIPTION	B & K-PRECISION PART NO.	SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.
FINAL ASSY (Continued)					
	Set Screw, 3 x 5mm x 0.5P (knobs)	633-010-9-002		3 x 6mm, 0.5P Phillips Flat Head Machine Screw (Standoff Sub Panels and SubPanel Frames)	634-202 9 002
	Snap Bushing (Trace Rotation)	380-593-9-002		3 x 6mm, 0.5P, Phillips Pan Head Machine Screw (Tilt Stand, PC Boards, Brackets, Case, Etc.)	634-202 9 006
	Standoff (Lever Switch)	759-232-9-001		3 x 10mm, 0.5P Phillips Pan Head Machine Screw (Feet)	634-238 9 002
	Standoff, 12.5mm long	759-232-9-004		3 x 12mm, 0.5P, Phillips Pan Head Machine Screw (Cord Wrap and CRT Clamp)	634-202-9 003
	Standoff, 18.5mm long	759-232-9-005		3 x 14mm, 0.5P Phillips Flat Head Machine Screw (Handle)	634-202-9 009
	Steel Strap, Handle (Inner)	746-076-9-002		4 x 8mm, 0.7P Phillips Pan Head Machine Screw (Transformer)	634-240-9-001
	Strain Relief	380-001-9-001			
	Switch Button, Gray	384-115-9-002			
	Switch Button, Red	384-079-9-003			
	Tilt Stand, (Wire Form)	804-024-9-001			
	Top Cover	253-145-9-001			

SWEEP MODE SWITCH LINE SELECT...PC BOARD ASSEMBLY**546-027-9-001****RESISTORS**d resistors are $\pm 5\%$, 1/4 W. See schematic diagram for value.

	10 k Ω , 1/4 W, $\pm 1\%$ Metal Film	015-144-1-002
	10 k Ω , 1/4 W, $\pm 1\%$ Metal Film	015-144-1-002
706,	100 k Ω , 1/4 W, $\pm 1\%$ Metal Film	015-144-1-003
	100 k Ω , 1/4 W, $\pm 1\%$ Metal Film	015-144-1-002
	2.0 k Ω , 1/4 W, $\pm 1\%$ Metal Film	015-144-2-001
/S104	10 k Ω , Potentiometer w/Switch (CH1 POSITION/PULL CHOP ONLY)	008-881-9-005
/S204	10 k Ω , Potentiometer w/Switch (CH2 POSITION/PULL INVERT)	008-881-9-005
/S406	10 k Ω /100 k Ω Dual Potentiometer w/Switch (LEVEL, HOLD OFF / ALT/CHOP SWITCH)	008-881-9-006
	10 k Ω Potentiometer (INTEN)	008-881-9-004
	200 k Ω , Potentiometer (FOCUS)	008-881-9-001
	10 k Ω Potentiometer (ILLUM)	008-881-9-004
	2 k Ω Potentiometer (ROTATION)	008-881-9-007
	100 k Ω Trimmer Potentiometer (FREQUENCY)	010-061-9-001

CAPACITORS

	1000 pF, $\pm 10\%$, 50 V, Ceramic	020-430-9-001
	0.1 μ F, $\pm 80\%$ -20%, 50 V, Ceramic	020-430-9-002
602	1000 pF, $\pm 80\%$ -20%, 6.3 KV, Ceramic	020-430-9-003
	47 μ F, $\pm 80\%$ -20%, 25 V, Electrolytic	022-328-9-001

C702, 703	.01 μ F, $\pm 1\%$, 100 V, Metalized, Polyester	025-250 9 002
C704	1 pF, ± 0.5 pF, 50 V, NPO Ceramic	031-073-9-001
C705	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073 9 002

SWITCHES

S302, S404	Pushbutton Switch, 4 Station (ALT, AUTO/NORM/SINGLE)	088-178 9 002
S601	Pushbutton Switch, 1 Station (ON/OFF)	088-178 9 001

DIODES

D405	1N4148	151-038-9-001
DS401, 603	LED, Red	158-076-9-001
DZ606 - 609	36 V, 2.2%, 500 mW, Zener	152-186 9 001

TRANSISTORS

Q614, 615	2SC1846R NPN	176-142 9 002
-----------	--------------------	---------------

INTEGRATED CIRCUITS

U701	4011B Quad 2-Input NAND Gate	308-144 9 001
------	------------------------------------	---------------

MISCELLANEOUS

DS604, 605	14 V, 80 mA Lamp	400-101-9-001
J9B, 13B	2 Pin PC Terminal, Right Angle Small	757-147-9-002
J21A	2 Pin PC Terminal, Large	757-148-9-002
J21B	2 Pin PC Terminal (Special)	757 147 9 001
J22	3 Pin PC Terminal, Large	757 148 9 003
J23A - 23E	5 Pin PC Terminal, Large	757 148 9 005
J33, 34	2 Pin IC Terminal, Small	757-144-9-002
	Shield, 18 x 47mm	256-274-9 003

VERTICAL INPUT OUTPUT, POWER SUPPLY & SWITCHING CIRCUIT PC BOARD ASSY**546-026-9-001****RESISTORS**d resistors are $\pm 5\%$, 1/4 W. See schematic diagram for value.

	1 M Ω , $\pm 1\%$, 1/2 W, Metal Film	015-124-1-004	R239, 240	681 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-6-810
	900 k Ω , $\pm 1\%$, 1/2 W, Metal Film	013-010-9-011	R247, 248	1.54 k Ω , $\pm 1\%$, 1/4 W, Metal Film	014-144-1-541
	111 k Ω , $\pm 1\%$, 1/4 W, Metal Film	013-034-9-036	R254, 255	1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-001
	990 k Ω , $\pm 1\%$, 1/2 W, Metal Film	013-010-9-012	R303, 304	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750
	10.1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	013-034-9-035	R310	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750
	470 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-474	R311, 312	90.9 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-9-098
	Resistor Network	012-047-9-002	R313	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750
126	121 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-210	R315	90.9 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-9-098
	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750	R325, 326	33 k Ω , $\pm 5\%$, 1 W, Metal Oxide	011-001-5-333
	56.2 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-5-622	R328, 329	47 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-473
	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750	R355	10 k Ω , $\pm 5\%$, Resistor Network	012-047-9-003
	56.2 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-5-622	R600, 601	3.9 k Ω , $\pm 5\%$, 2 W, Metal Oxide	004-236-9-004
140	681 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-6-810	R603	100 Ω , $\pm 5\%$, 1 W, Metal Oxide	011-001-5-101
148	1.54 k Ω , $\pm 1\%$, 1/4 W, Metal Film	014-144-1-541	R607	121 k Ω , $\pm 1\%$, 1/2 W, Metal Film	015-124-1-213
155	1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-001	R608	10.1 k Ω , $\pm 0.5\%$, 1/4 W, Metal Film	017-144-1-012
	1 M Ω , $\pm 1\%$, 1/2 W, Metal Film	015-124-1-004	R609	1.0 Ω , $\pm 5\%$, 1 W, Metal Oxide	011-001-5-109
	900 k Ω , $\pm 1\%$, 1/2 W, Metal Film	013-010-9-011	R612	2.2 Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-229
	111 k Ω , $\pm 1\%$, 1/4 W, Metal Film	013-034-9-036	R613	100 Ω , $\pm 5\%$, 1 W, Metal Oxide	011-001-5-101
	990 k Ω , $\pm 1\%$, 1/2 W, Metal Film	013-010-9-012	R614	68 Ω , $\pm 5\%$, 1 W, Metal Oxide	011-001-5-680
	10.1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	013-034-9-035	R616	3.92 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-3-921
	470 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-474	R617	9.09 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-9-091
	Resistor Network	012-047-9-002	R619	12.1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-212
226,	121 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-210	R622	12.1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-212
	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750	R623	100 Ω , $\pm 5\%$, 1 W, Metal Oxide	011-001-5-101

SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.	SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.
VERTICAL INPUT OUTPUT, POWER SUPPLY & SWITCHING CIRCUIT PC BOARD ASSY					
(Continued)					
4, 625	2.2 M Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-225	C127	22 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-068-9-003
01, 102, 01	250 Ω , $\pm 15\%$, Thermistor	005-022-9-001	C128	10 μ F, $\pm 80/-20\%$, 50 V, Electrolytic	022-390-9-001
01	22 k Ω , Trimmer Potentiometer (STEP BAL)	010-061-9-010	C201	.022 μ F, $\pm 5\%$, 630 V, Metalized Film Polyester	025-282-9-009
02	100 Ω , Trimmer Potentiometer (X5 GAIN)	010-061-9-006	C202	33 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-010
03	470 Ω , Trimmer Potentiometer (1ST COMP)	010-061-9-011	C203	270 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-006
04	22 k Ω , Trimmer Potentiometer (MAG DC BAL)	010-061-9-010	C204	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-002
06	22 k Ω , Trimmer Potentiometer (VAR DC BAL)	010-061-9-010	C205	2200 pF, $\pm 5\%$, 400 V, Metalized Film Polyester	025-282-9-008
07	220 Ω , Trimmer Potentiometer (2ND COMP)	010-061-9-008	C206	10 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-009
08	1 k Ω , Trimmer Potentiometer (CH1 GAIN)	010-061-9-007	C207	1000 pF, $\pm 10\%$, 500 V, Ceramic	020-430-9-006
09	100 Ω , Trimmer Potentiometer (X-GAIN)	010-061-9-006	C208, 209	0.1 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-430-9-002
10	1 k Ω , Trimmer Potentiometer (CH1 TRIG DC OFFSET)	010-061-9-007	C210	1000 pF, $\pm 10\%$, 500 V, Ceramic	020-430-9-006
112	2.2 k Ω , Trimmer Potentiometer (SIGNAL OUT DC OFFSET)	010-061-9-009	C211	10 μ F, $\pm 80/-20\%$, 50 V, Electrolytic	022-390-9-001
201	22 k Ω , Trimmer Potentiometer (STEP BAL)	010-061-9-010	C212	15 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-004
202	100 Ω , Trimmer Potentiometer (X GAIN)	010-061-9-006	C213	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-002
203	470 Ω , Trimmer Potentiometer (1ST COMP)	010-061-9-011	C214, 215	5 pF, ± 0.5 pF, 500 V, NPO Ceramic	031-073-9-008
204	22 k Ω , Trimmer Potentiometer (MAG DC BAL)	010-061-9-010	C216, 217	82 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-007
206	22 k Ω , Trimmer Potentiometer (VAR DC BAL)	010-061-9-010	C218	47 pF, 500 V, NPO Ceramic	031-073-9-005
207	220 Ω , Trimmer Potentiometer (2ND COMP)	010-061-9-008	C219, 220, 222, 224	.01 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-380-9-001
208	1 k Ω , Trimmer Potentiometer (CH2 GAIN)	010-061-9-007	C225, 226	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-002
301	470 Ω , Trimmer Potentiometer (ADD BAL)	010-061-9-011	C227	22 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-068-9-003
302	2.2 k Ω , Trimmer Potentiometer (3RD COMP)	010-061-9-009	C228	10 μ F, $\pm 80/-20\%$, 50 V, Electrolytic	022-390-9-001
501	1 k Ω , Trimmer Potentiometer (+12 V ADJ)	010-061-9-007	C301	5 pF, ± 0.5 pF, 500 V, NPO Ceramic	031-073-9-008
CAPACITORS			C302, 303	15 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-004
2	100 pF, $\pm 5\%$, 50 V, NPO Ceramic	201-069-9-003	C304, 305	.01 μ F, $\pm 5\%$, 100 V, Polyester	025-282-9-006
3	22 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-068-9-003	C306, 307	0.47 pF, 0.25 pF, 500 V, NPO Ceramic	031-073-9-011
5	100 pF, $\pm 5\%$, 50 V, NPO Ceramic	201-069-9-003	C308, 309	.047 μ F, $\pm 5\%$, 250 V, Metalized Film Polyester	025-282-9-007
6	68 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-012	C310	0.1 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-430-9-002
7	5 pF, ± 0.5 pF, 500 V, NPO Ceramic	031-073-9-008	C311	.022 μ F, $\pm 5\%$, 630 V, Metalized Film Polyester	025-282-9-009
8	100 pF, $\pm 5\%$, 50 V, NPO Ceramic	201-069-9-003	C312	0.1 μ F, $\pm 5\%$, 100 V, Polyester	025-282-9-002
9	22 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-068-9-003	C313	.022 μ F, $\pm 5\%$, 630 V, Metalized Film Polyester	025-282-9-009
01	100 pF, $\pm 5\%$, 50 V, NPO Ceramic	201-069-9-003	C314	1.0 μ F, $\pm 80/-20\%$, 160 V, Electrolytic	021-085-9-001
02	68 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-012	C315, 316	.01 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-380-9-001
03	.022 μ F, $\pm 5\%$, 630 V, Metal Film Polyester	025-282-9-009	C317	1500 pF, $\pm 10\%$, 50 V, Ceramic	020-430-9-009
04	33 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-010	C318	1000 pF, $\pm 10\%$, 500 V, Ceramic	020-430-9-006
05	270 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-006	C319, 320	.01 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-380-9-001
06	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-002	C321, 322	100 μ F, $\pm 80/-20\%$, 25 V, Electrolytic	022-328-9-002
07	2200 pF, $\pm 5\%$, 400 V, Metalized Film Polyester	025-282-9-008	C323, 324	10 μ F, $\pm 80/-20\%$, 50 V, Electrolytic	022-390-9-001
08	10 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-009	C325	10 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-009
09	1000 pF, $\pm 10\%$, 500 V, Ceramic	020-430-9-006	C603	47 μ F, $\pm 80/-20\%$, 200 V, Electrolytic	021-085-9-002
10	0.1 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-430-9-002	C604	4.7 μ F, $\pm 80/-20\%$, 350 V, Electrolytic	021-085-9-003
11	1000 pF, $\pm 10\%$, 500 V, Ceramic	020-430-9-006	C605	1.0 μ F, $\pm 80/-20\%$, 160 V, Electrolytic	021-085-9-001
12	10 μ F, $\pm 80/-20\%$, 50 V, Electrolytic	022-390-9-001	C606	47 μ F, $\pm 80/-20\%$, 25 V, Electrolytic	022-328-9-001
13	15 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-004	C607, 608	1000 μ F, $\pm 80/-20\%$, 25 V, Electrolytic	022-335-9-004
14	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-002	C609, 610	.022 μ F, $\pm 5\%$, 100 V, Polyester	025-282-9-003
15	5 pF, ± 0.5 pF, 500 V, NPO Ceramic	031-073-9-008	VC101	3-10 pF Trimmer	028-114-9-002
16	82 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-007	VC102	2.5-6 pF Trimmer	028-114-9-001
17	47 pF, 500 V, NPO Ceramic	031-073-9-005	VC103	4.5-20 pF Trimmer	028-114-9-003
18, 120, 22	.01 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-380-9-001	VC104	2.5-6 pF Trimmer	028-114-9-001
23	10 μ F, $\pm 80/-20\%$, 50 V, Electrolytic	022-390-9-001	VC105	4.5-20 pF Trimmer	028-114-9-003
24	.01 μ F, $\pm 80/-20\%$, 50 V, Ceramic	020-380-9-001	VC106	7.5-50 pF Trimmer	028-114-9-004
25, 126	220 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-073-9-002	VC201	3-10 pF Trimmer	028-114-9-002
			VC202	2.5-6 pF Trimmer	028-114-9-001
			VC203	4.5-20 pF Trimmer	028-114-9-003
			VC204	2.5-6 pF Trimmer	028-114-9-001
			VC205	4.5-20 pF Trimmer	028-114-9-003
			VC206	7.5-50 pF Trimmer	028-114-9-004
			VC301	4.5-20 pF Trimmer	028-114-9-003
SWITCHES					
			S101	3 Position Lever Switch (AC GND DC)	080-031-9-003
			S103/VR105	Rotary Switch w/Potentiometer (VOLTS/DIV Attenuator)	083-325-9-001
			S201	3 Position Lever Switch (AC GND DC)	080-031-9-003
			S203/VR205	Rotary Switch w/Potentiometer (VOLTS/DIV Attenuator/PULL X5 MAG / VARIABLE)	083-325-9-001
			S301	4 Position Lever Switch (VERT MODE)	080-031-9-001

SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.	SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.
---------------------	-------------	-----------------------------	---------------------	-------------	-----------------------------

VERTICAL INPUT OUTPUT, POWER SUPPLY & SWITCHING CIRCUIT PC BOARD ASSY

(Continued)

DIODES					
BD601, 602	2 A, 600 V, Bridge (2W06M)	157-039-9-001	Q313, 314	2SC2570A NPN	176-222-9-003
D101 - 107,	1N4148	151-038-9-001	Q315, 316	2SA844D PNP	177-021-9-001
201 - 206,			Q601	2SB861C PNP	173-024-9-003
301 - 316,			Q602	2SD880Y NPN Power	172-082-9-001
601, 602			Q603	2SB834Y PNP Power	173-024-9-004
DZ101, 201	3.3 V, $\pm 3\%$, 500 mW, Zener	152-186-9-003	Q604	2SD880Y NPN Power	172-082-9-001
DZ301, 302	2.2 V, $\pm 4.5\%$, 500 mW, Zener	152-186-9-002	INTEGRATED CIRCUITS		
DZ601, 602	13 V, ± 4.7 - $\pm 3.1\%$, 500 mW, Zener	152-186-9-005	U101	3140 Operational Amplifier	308-191-9-001
DZ603	5.6 V, ± 1.79 - $\pm 2.5\%$, 500 mW, Zener	152-186-9-004	U102	3086 Transistor Array	307-087-9-001
TRANSISTORS			U201	3140 Operational Amplifier	308-191-9-001
Q101	2SC1730K NPN	176-222-9-001		3086 Transistor Array	307-087-9-001
Q102	2SK121-3 FET	182-101-9-002	U202	74LS74AN Dual D Flip-Flop	307-361-9-006
Q103	2SC945Q NPN	176-059-9-003	U301	74S00N Quad 2-Input NAND Gate	307-100-9-001
Q104	2SA844D PNP	177-021-9-001	U302 - 304	4558C BCD-TO-7 Segment	
Q105	2SC945Q NPN	176-059-9-003	U601, 602	Decoder	307-435-9-003
Q106, 107	2SA1206K PNP	177-065-9-001	INDUCTORS AND TRANSFORMERS		
Q108, 109	2SA838C PNP	177-036-9-001	L301, 302	0.14 μ H, $\pm 20\%$ Coil	047-075-9-002
Q110	2SC1730K NPN	176-222-9-001	MISCELLANEOUS		
Q111, 112	2SA838C PNP	177-036-9-001	J1	2 Pin PC Terminal, Small	757-144-9-002
Q201	2SC1730K NPN	176-222-9-001	J2A, 4A	5 Pin PC Terminal, Small	757-149-9-002
Q202	2SK121-3 FET	182-101-9-002	J5A	2 Pin PC Terminal, Small	757-144-9-002
Q203	2SC945Q NPN	176-059-9-003	J6, 7	1 Pin PC Terminal, Large	757-148-9-001
Q204	2SA844D PNP	177-021-9-001	J8A	4 Pin PC Terminal, Small	757-149-9-003
Q205	2SC945Q NPN	176-059-9-003	J9A	2 Pin PC Terminal, Small	757-144-9-002
Q206, 207	2SA1206K PNP	177-065-9-001	J24	5 Pin PC Terminal, Large	757-148-9-005
Q208 - 213	2SA838C PNP	177-036-9-001	J25A	2 Pin PC Terminal, Small	757-144-9-002
Q301, 302	2SA1206K PNP	177-065-9-001	J26A	5 Pin PC Terminal, Small	757-149-9-002
Q303 - 305	2SC1730K NPN	176-222-9-001	J27A, 28A	6 Pin PC Terminal, Small	757-149-9-004
Q306, 307	2SA1206K PNP	177-065-9-001		Heat Sink (for Q309 - 312)	747-164-9-002
Q308	2SC1730K NPN	176-222-9-001		Heat Sink (for Q601, 603, 604)	747-164-9-003
Q309	2SA1360-0 PNP	173-024-9-002		Heat Sink	747-164-9-004
Q310, 311	2SC3423-0 NPN	172-082-9-004		Insulator, Transistor	347-140-9-001
Q312	2SA1360-0 PNP	173-024-9-002			

HORIZ SWEEP, TRIGGER & HIGH VOLTAGE PC BOARD ASSEMBLY

546-025-9-001

RESISTORS					
Unlisted resistors are $\pm 5\%$, 1/4 W. See schematic diagram for value.					
R402	1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-001	VR403	10 k Ω , Trimmer Potentiometer (TRIG BAL)	010-061-9-002
R411	1 M Ω , $\pm 1\%$, 1/2 W, Metal Film	015-124-1-004	VR404	470 k Ω , Trimmer Potentiometer (1 μ S ADJ)	010-061-9-005
R417, 418	681 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-6-810	VR405	10 k Ω , Trimmer Potentiometer (1mS ADJ)	010-061-9-002
R459	33.2 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-3-322	VR602	2.2 M Ω , Trimmer Potentiometer (SUB FOCUS)	010-061-9-003
R460	22.1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-2-212	VR603	10 k Ω , Trimmer Potentiometer (SUB INTEN)	010-033-9-003
R474	2.21 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-2-211	VR604	100 k Ω , Trimmer Potentiometer (ASTIG)	010-061-9-001
R481	Resistor Network	012-047-9-001	CAPACITORS		
R483	1.62 k Ω , $\pm 1\%$, 1/4 W, Metal Film	014-144-1-621	C402	.01 μ F, ± 80 - $\pm 20\%$, 50 V, Ceramic	020-380-9-001
R486	475 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-4-750	C403	10 μ F, ± 80 - $\pm 20\%$, 50 V, Electrolytic	022-390-9-001
R487	3.92 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-3-921	C404	.022 μ F, $\pm 5\%$, 100 V, Polyester	025-282-9-003
R503	56.2 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-5-628	C405, 406	47 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-005
R504 - 507	5.62 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-5-621	C407	470 pF, $\pm 10\%$, 50 V, Ceramic	020-430-9-008
R508 - 510	1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-001	C408	10 μ F, ± 80 - $\pm 20\%$, 50 V, Electrolytic	022-390-9-001
R511	562 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-5-620	C410, 411	47 μ F, ± 80 - $\pm 20\%$, 25 V, Electrolytic	022-328-9-001
R512, 513	332 Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-3-320	C412	10 μ F, ± 80 - $\pm 20\%$, 50 V, Electrolytic	022-390-9-001
R515	100 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-104	C413	1.0 μ F, $\pm 10\%$, 35 V, Tantalum	027-096-9-001
R516	100 k Ω , $\pm 1\%$, 1/2 W, Metal Film	015-124-1-003	C414	100 μ F, ± 80 - $\pm 20\%$, 25 V, Electrolytic	022-328-9-002
R518	100 k Ω , $\pm 1\%$, 1/2 W, Metal Film	015-124-1-003	C415	0.1 μ F, $\pm 5\%$, 100 V, Polyester	025-282-9-002
R523	100 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-104	C416	47 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-005
R626	100 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-003	C417	47 μ F, ± 80 - $\pm 20\%$, 25 V, Electrolytic	022-328-9-001
R630	8.25 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-8-251	C420, 422	1000 pF, $\pm 5\%$, 500 V, Ceramic	020-430-9-006
R631	12.1 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-212	C421	10 μ F, ± 80 - $\pm 20\%$, 50 V, Electrolytic	022-390-9-001
R634	1.0 Ω , $\pm 1\%$, 1 W, Metal Oxide	004-236-9-002	C423	.01 μ F, $\pm 5\%$, 100 V, Polyester	025-282-9-001
R638	2.2 M Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-225	C424	47 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-005
R639, 640	10 M Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-106	C425	47 μ F, ± 80 - $\pm 20\%$, 25 V, Electrolytic	022-328-9-001
R645	1.5 M Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-155	C426	1000 pF, $\pm 5\%$, 100 V, Metal Film	
R646	6.8 M Ω , $\pm 1\%$, 1.6 W, Metal Glaze	004-236-9-003		Polyester	025-282-9-004
R647	10 M Ω , $\pm 1\%$, 2.5 W, Metal Glaze	004-236-9-001		100 pF, $\pm 5\%$, 50 V, NPO Ceramic	031-069-9-003
R648, 649	10 M Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-106		1.0 μ F, $\pm 5\%$, 100 V, Metalized Film	
R651	1.5 M Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-155		Polyester	025-282-9-005
R657, 658	47 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-473	C427	.01 μ F, ± 80 - $\pm 20\%$, 50 V, Ceramic	020-380-9-001
R661, 662	47 k Ω , $\pm 5\%$, 1/2 W, Carbon Film	002-102-5-473	C428	15 pF, $\pm 5\%$, 500 V, NPO Ceramic	031-073-9-004
R670	100 k Ω , $\pm 1\%$, 1/4 W, Metal Film	015-144-1-003	C429	47 μ F, ± 80 - $\pm 20\%$, 25 V, Electrolytic	022-328-9-001
VR401	47 k Ω , Trimmer Potentiometer (X-AXIS DC-OFFSET)	010-061-9-004	C430		
			C431		

SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.	SCHEMATIC SYMBOL	DESCRIPTION	B & K-PRECISION PART NO.
HORIZ SWEEP, TRIGGER & HIGH VOLTAGE PC BOARD ASSEMBLY					
(Continued)					
432	.01 μ F, +80/-20%, 50 V, Ceramic	020-380-9-001	Q410	2SK40C FET	182-101-9-003
433, 434	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q411	2SK117BL FET	182-101-9-001
435	100 pF, $\pm$ 5%, 50 V, NPO Ceramic	031-069-9-003	Q412	2SA1015-GR PNP	177-057-9-001
501	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q413	2SA838C PNP	177-036-9-001
502 - 506	.01 μ F, +80/-20%, 500 V, Ceramic	020-430-9-007	Q414, 415	2SC1730K NPN	176-222-9-001
507	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q416	2SA844D PNP	177-021-9-001
611	1.0 μ F, $\pm$ 10%, 35 V, Tantalum	027-096-9-001	Q417	2SC945Q NPN	176-059-9-003
612	4700 pF, $\pm$ 10%, 50 V, Ceramic	020-430-9-005	Q418	2SC1730K NPN	176-222-9-001
613	.022 μ F, $\pm$ 5%, 100 V, Polyester	025-282-9-003	Q419, 420	2SC945Q NPN	176-059-9-003
614	200 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-002	Q421, 422	2SA844D PNP	177-021-9-001
618	4700 pF, +80/-20%, 3 KV, Ceramic	020-430-9-004	Q423	2SC945Q NPN	176-059-9-003
619	1000 pF, +80/-20%, 6.3 KV, Ceramic	020-430-9-003	Q424	2SA844D PNP	177-021-9-001
620	.01 μ F, +80/-20%, 500 V, Ceramic	020-430-9-007	Q425, 426	2SK117BL FET	182-101-9-001
621 - 625	1000 pF, +80/-20%, 6.3 KV, Ceramic	020-430-9-003	Q427	2SC945Q NPN	176-059-9-003
626	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q428	2SA844D PNP	177-021-9-001
627	.01 μ F, +80/-20%, 500 V, Ceramic	020-430-9-007	Q429	2SC1843E NPN	176-222-9-002
628	.01 μ F, +80/-20%, 50 V, Ceramic	020-380-9-001	Q430, 431	2SA844D PNP	177-021-9-001
629	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q501, 502	2SA1015-GR PNP	177-057-9-001
630	220 pF, $\pm$ 5%, 50 V, NPO Ceramic	031-073-9-002	Q503, 504	2SC945Q NPN	176-059-9-003
631	.01 μ F, +80/-20%, 50 V, Ceramic	020-380-9-001	Q505 - 507	2SC1730K NPN	176-222-9-001
632	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q508	2SA838C PNP	177-036-9-001
633	.01 μ F, +80/-20%, 500 V, Ceramic	020-430-9-007	Q509	2SB648A-B PNP Power	173-024-9-001
634	.022 μ F, $\pm$ 5%, 100 V, Polyester	025-282-9-003	Q510, 511	2SD668A-C NPN Power	172-082-9-003
635, 636	10 μ F, +80/-20%, 50 V, Electrolytic	022-390-9-001	Q512	2SB648A-B PNP Power	173-024-9-001
637	22 pF, $\pm$ 10%, 2 KV, NPO Ceramic	031-073-9-003	Q605	2SD880Y NPN Power	172-082-9-001
638	.01 μ F, +80/-20%, 50 V, Ceramic	020-380-9-001	Q606 - 609	2SC2371K NPN Power	172-082-9-002
SWITCHES					
401, 402	Lever Switch (SOURCE, COUPLING)	080-031-9-002	Q610, 611	2SC1730K NPN	176-222-9-001
403	Lever Switch (SLOPE)	080-031-9-001	Q612	2SA844D PNP	177-021-9-001
405	Rotary Switch (TIME/DIV)	083-324-9-001	Q613	2SK117BL FET	182-101-9-001
DIODES					
401, 402	1N4148	151-038-9-001	U401	74S00 Quad 2-Input NAND Gate	307-028-9-001
403	1SS86 (30 mA, 3 V)	151-156-9-002	U402	74LS112AN Dual JK Flip-Flop	307-259-9-025
404, 406, 407	1N4148	151-038-9-001	U403	TL081CP Operational Amplifier	307-464-9-001
408	1SS86 (30 mA, 3 V)	151-156-9-002	U404	Triple 2CH Analog Multiplexer	308-375-9-003
409 - 420	1N4148	151-038-9-001	U603	TL081CP Operational Amplifier	307-464-9-001
501	1SS86 (30 mA, 3 V)	151-156-9-002	INDUCTORS AND TRANSFORMERS		
502, 503	1N4148	151-038-9-001	L601	100 μ H, $\pm$ 10% Coil	047-075-9-001
D504	1SS83 (200 mA, 250 V)	151-084-9-001	T601	Pulse Transformer	064-032-9-001
603, 605, 606	1N4148	151-038-9-001	MISCELLANEOUS		
609 - 613	1SS83 (200 mA, 250 V)	151-084-9-001	DS601, 602	NE-2 Neon Lamp	401-002-9-001
614	200 mA, 2 KV	151-156-9-001	J5B	2 Pin PC Terminal, Small	757-144-9-002
615, 616	1SS83 (200 mA, 250 V)	151-084-9-001	J10	1 Pin PC Terminal, Large	757-148-9-001
617 - 620	1N4148	151-038-9-001	J11A, 12A	5 Pin PC Terminal, Small	757-149-9-002
2401	3.3 V, $\pm$ 3%, 500 mW, Zener	152-186-9-003	J13A	2 Pin PC Terminal, Small	757-144-9-002
2402	5.6 V, $\pm$ 1.79/-2.5%, 500 mW, Zener	152-186-9-004	J14	3 Pin PC Terminal, Small	757-149-9-001
2604, 605	2.2 V, $\pm$ 4.5%, 500 mW, Zener	152-186-9-002	J15A, 15B,	2 Pin PC Terminal, Small	757-144-9-002
2610	5.6 V, $\pm$ 1.79/-2.5%, 500 mW, Zener	152-186-9-004	J16, 17	3 Pin PC Terminal, Small	757-149-9-001
TRANSISTORS					
401, 402	2SA838C PNP	177-036-9-001	J18, 19	1 Pin PC Terminal, Large	757-148-9-001
403	2SK121-3 FET	182-101-9-002	J25B	2 Pin PC Terminal, Small	757-144-9-002
404, 405	2SC1730K NPN	176-222-9-001	J29	2 Pin PC Terminal, Large	757-148-9-002
406 - 409	2SA844D PNP	177-021-9-001	J30	5 Pin PC Terminal, Large	757-148-9-005
			J31	3 Pin PC Terminal, Large	757-148-9-003
			J32	2 Pin PC Terminal, Small	757-144-9-002
				Heat Sink	747-164-9-001
				Insulator, Transistor (For Q605)	347-140-9-001
				Multiplier Assembly	524-020-9-001

CALIBRATION PROCEDURE

WARNING

The following instructions are for use by qualified service personnel only. To avoid electrical shock, do not perform servicing unless qualified to do so.

High voltage up to 12 kV when covers are removed and the unit is operating. Remember that high voltage may be retained indefinitely on high voltage capacitors. Also remember that ac line voltage is present on line voltage input circuits (including the fuse holder, line cord receptacle, and POWER switch) anytime the instrument is plugged into an ac outlet, even if turned off. Unplug the oscilloscope and discharge high voltage capacitors before performing service procedures unless it is necessary to have the unit powered up.

GENERAL

The unit was carefully checked and calibrated at the factory prior to shipment. After the oscilloscope has been used for a period of time, it should be calibrated to maintain instrument accuracy. Calibration is required if repairs have been made in a circuit affecting calibration. Location of the calibration adjustments is shown in Fig. 1 and Fig. 2. Keep in mind that some calibration adjustments require high precision test instruments. Those adjustments should be attempted only if the proper test equipment is available and you are experienced in its use. The unit should be calibrated at an ambient temperature of 20 degrees C (± 5 degrees C). Before making adjustments connect the unit to AC line voltage, 50/60 Hz line source and allow at least 30 minutes of warmup time before proceeding. The following test equipment is required for complete calibration:

- B & K-Precision Model 2906 Multimeter or equivalent.
- B & K-Precision Model 1400 Oscilloscope Calibrator or equivalent.
- B & K-Precision Model 1655 Variable AC Power Supply or equivalent with 120 V, 3 A capacity.
- B & K-Precision Model PR-28 High Voltage Multiplier Probe or equivalent with capability of measuring at least 12 kV.

NOTE

All voltage measurements are to be taken with respect to earth (chassis) ground unless otherwise noted.

Calibrating procedures MUST be done in sequence.

DC SUPPLY ADJUSTMENTS

Before you start to calibrate the oscilloscope, its DC supply voltage should be checked and adjusted.

DC SUPPLY

Check the +12 V supply voltage and adjust if necessary. The other supply voltages should be checked and adjusted only after the +12 V supply voltage has been completed.

Connect the digital voltmeter (DVM) between +12V and ground. If necessary, adjust 12V ADJ for a +12 V ± 0.05 V reading on the voltmeter.

VOLTAGE SUPPLY

Connect the DVM between -12V and ground. Acceptable limits are -12 V ± 0.2 V.

Connect the DVM between +5V and ground. Acceptable limits are +5 V ± 0.25 V.

Connect the DVM between +145V and ground. Acceptable limits are +145 V ± 5 V.

VOLTAGE SUPPLY(S)

Connect the DVM between -HV and ground.

Measure the voltage using a high voltage probe. Acceptable limits are between -1725 V and -1875 V.

The output of the multiplier should be approximately +10 kV

CIRCUIT ADJUSTMENT

INTENSITY ADJUSTMENT

Set up the oscilloscope with the TIME/DIV switch set to 1 mS to display a single horizontal trace on the screen.

2. Turn the HOLD OFF knob to NORM and set the white mark of the INTENSITY control to the 10 o'clock position.
3. Adjust VR603 (SUB INTEN) until the trace displayed on the screen is just barely visible.

FOCUS ADJUSTMENT

1. Set up the oscilloscope with the FOCUS control set to display the white dot in the upright or noon position.
2. Adjust VR602 (SUB FOCUS) to obtain the best focus.

ASTIGMATISM ADJUSTMENT

1. Set up the oscilloscope with the TIME/DIV switch set to X-Y and the input coupling switch set to GND.
2. Use the position controls to display the beam spot in the center of the CRT screen.
3. Set the INTENSITY control for a small spot and turn the FOCUS control to obtain the sharpest image possible.
4. Adjust VR604 (ASTIG) so that the shape of the beam spot becomes as true a circle as possible.

VERTICAL SYSTEM ADJUSTMENT

DC BALANCE ADJUSTMENT

1. Set the channel 1 (CH 1) [channel 2 (CH 2)] AC-GND-DC switch to GND and the VERT MODE switch to CH 1 [CH 2] to display the trace on the CRT screen.
2. Set the VOLTS/DIV switch to 5 mV.
3. Position the trace to the horizontal center line and then change the VOLTS/DIV switch to 10 mV.
4. Check that the trace is within ± 0.05 division of the center horizontal line.
5. Adjust VR101 [VR201] (STEP BAL) for a trace at the center line.
6. Repeat steps 2 through 5 until a division shift of less than ± 0.05 is noted when changing the VOLTS/DIV setting.
7. Check the trace division for the other VOLTS/DIV ranges. The trace for each range must be within ± 0.15 of the center horizontal line.
8. Repeat procedure for CH 2 using data shown in brackets.

X5 MAGNIFICATION DC BALANCE ADJUSTMENT

1. Set the CH 1 [CH 2] AC-GND-DC switch to GND and the VERT/MODE switch to CH 1 [CH 2].
2. Turn the CH 1 [CH 2] VOLTS/DIV VAR knob to CAL and the VOLTS/DIV setting to 10 mV.
3. Position the trace to the horizontal center line.
4. Pull out the VOLTS/DIV VAR knob and adjust VR104 [VR204] (MAG DC) for a trace at the horizontal center line.
5. Push the VOLTS/DIV VAR knob back to its normal position.
6. Repeat steps 3 through 5 until a horizontal center line division shift of less than ± 0.2 is obtained.
7. Repeat procedure for CH 2 using data shown in brackets.

VARIABLE DC BALANCE ADJUSTMENT

1. Set the CH 1 [CH 2] AC-GND-DC switch to GND and the VERT MODE switch to CH 1 [CH 2] to display a trace on the CRT screen.
2. Set the VOLTS/DIV switch to 10 mV.




Fig. 1. Adjustment Locations (Top View)




Fig. 2. Adjustment Locations (Bottom View)

Position the trace to the horizontal center line.

Turning the VAR knob from left to right adjust VR106 [VR206] (VAR DC) until a horizontal center line division shift of less than ± 0.3 is obtained.

Pull out the VOLTS/DIV VAR knob and observe the shift of the trace. The shift division must be within ± 0.6 of the horizontal center line.

Repeat procedure for CH 2 using data shown in brackets.

BALANCE ADJUSTMENT

Set both the CH 1 and CH 2 AC-GND-DC switches to GND and both VOLTS/DIV switches to 10 mV.

Set the VERT MODE switch separately to the CH1 and CH2 positions to position the trace to the horizontal center line.

Set the VERT MODE switch to ADD.

Adjust VR301 (ADD BAL) to position the trace to the horizontal center line.

Set the VERT MODE switch to each position (CH1, CH2, DUAL) The trace division must be within ± 0.5 of the center horizontal line.

SENSITIVITY CALIBRATION

Set both CH 1 and CH 2 VOLTS/DIV switches to 10 mV. Turn both VOLTS/DIV VAR knobs to CAL and set both AC-GND-DC switches to DC. Set the VERT MODE switch to CH 1.

Connect the standard amplitude calibrator to both the input connectors and set for a 50 mV p-p square-wave signal.

Adjust VR108 (CH 1 GAIN) for a display of five divisions.

Set the VERT MODE switch to DUAL and both the AC-GND-DC switches to GND.

Turn the CH 1 POS control to position the trace at the horizontal center line.

Pull out and turn the CH 2 POS control to position the trace at the horizontal center line.

Set the VERT MODE switch to ADD and the AC-GND-DC switch to DC.

Adjust VR208 (CH 2 GAIN) to align the CRT screen.

Set the VERT MODE switch to CH 1.

Set the standard amplitude calibrator for an eight division 50 kHz sinewave signal.

Set the TIME/DIV switch to 0.2 ms.

Set the VERT MODE switch to ADD and check the division of the AC amplitude.

Repeat steps 4 through 9 as necessary until an AC amplitude division less than 0.06 is obtained.

MAGNIFICATION SENSITIVITY CALIBRATION

Set the VOLTS/DIV switch to 10 mV and the input coupling switch to DC.

Turn both the VOLTS/DIV VAR knobs to CAL and pull out the knob to set the X5 MAG.

Connect the standard amplitude calibrator to the input connectors and set for a 10 mV p-p 1 kHz square-wave signal.

Adjust VR102 [VR202] (X5 MAG GAIN) for a five division display.

Repeat procedure for CH 2 using data shown in brackets.

SQUARE-WAVE CHARACTERISTIC ADJUSTMENT/FREQUENCY RESPONSE CHECK

Set both the VOLTS/DIV switches to 10 mV, the TIME/DIV switch to 0.2 μ s, and both AC-GND-DC switches to AC.

Using a 50 Ω termination and cable, connect the 20 MHz sinewave signal to CH 1 [CH 2] input to get a four division display.

Adjust VC105 [VC205] (1ST COMP) and VC106 [VC206] (2ND COMP) for the maximum amplitude of signal wave on the CRT screen.

Using a digital multimeter (DMM), Adjust VR107 [VR207] (2ND COMP) to get a 90 Ω reading.

Using a 50 Ω termination and cable, connect the fast-rise positive output (1 MHz) of the square-wave generator to the input.

Adjust the square-wave generator output for a six division display.

7. Adjust VR302 and VC301 (3RD COMP) so that the square-wave is flat.
8. Readjust VR107 [VR207] (2ND COMP) to get a flat (top) square-wave form.
9. Readjust VR103 [VR203] (1ST COMP) for an overshoot of 0.1 division and ringing of waveform of less than 0.3 division.
10. Connect the sinewave generator to the input connectors and set for a 100 kHz, 80 mV p-p, eight division display.
11. Change only the frequency of the sinewave generator to 43 MHz. The amplitude of the sinewave on the CRT screen must be above 5.6 division display.
12. Pull out the VOLTS/DIV VAR knob to set at X5 MAG. Turn the VOLTS/DIV switch to 5 mV.
13. Set the sinewave generator for a 100 KHz, 8 mV p-p, eight division display signal.
14. Change only the frequency of the sinewave generator to 21 MHz. The amplitude of the sinewave on the CRT screen must be above a 5.6 division display.
15. Repeat procedure for CH 2 using data shown in brackets.

PHASE COMPENSATION ADJUSTMENT

1. Set the CH 1 [CH 2] VOLTS/DIV switch to 0.1 V. Set the CH 1 [CH 2] AC-GND-DC switch to DC. Set the VERT MODE switch to CH 1 [CH 2]. Turn the VOLTS/DIV VAR knob of CH 1 [CH 2] to CAL.
2. Set the oscilloscope calibration generator for a 0.5 V, five division display square-wave signal.
3. Adjust trimmer capacitor VC102 [VC202] (1/10 PHASE) for a square-wave that is an ideal waveform. (See Fig 3 for Square Wave Characteristics)




Fig. 3. Adjusting 1 kHz Square Wave Characteristics

4. Change the CH 1 [CH 2] VOLTS/DIV switch to 1 V.
5. Set the oscilloscope calibration generator for a 5 V, five division display square-wave signal.
6. Adjust trimmer capacitor VC104 [VC204] (1/100 PHASE) for an ideal square-wave form.
7. Repeat procedure for CH 2 using data shown in brackets.

INPUT CAPACITY ADJUSTMENT

1. Set the CH 1 [CH 2] VOLTS/DIV switch to 10 mV. Set the VERT MODE switch to CH 1 [CH 2]. Set the CH 1 [CH 2] AC-GND-DC switch to DC.
2. Connect the oscilloscope calibration generator through the 10:1 probe to the input connector. Set for a 1 kHz, 500 mV, five division display square-wave signal. Then, adjust the trimmer capacitor of the probe for an ideal square-wave form.
3. Change the CH 1 [CH 2] VOLTS/DIV switch to 0.1 V.
4. Adjust the oscilloscope calibration generator for a five division display.
5. Adjust trimmer capacitor VC101 [VC201] (1/10 CAP) for an ideal square-wave form.
6. Same as 3 but 1 V.
7. Same as 4.
8. Same as 5 but VC103 [VC203] (1/100 CAP).
9. Repeat procedure for CH 2 using data shown in brackets.

BASE ADJUSTMENT

SWEEP TIME CALIBRATION

Set the TIME/DIV switch to 1 mS. Turn the SWEEP/VAR knob to CAL. Set the VERT MODE switch to CH 1.

Set the time mark generator to 1 mS (1 kHz pulse train) time marks.

Adjust VR405 (A-1 mS) so that the time marks coincide with the middle eight graticule lines.

Change the TIME/DIV switch to 1 μ S. Change the time mark generator for 1 μ S time marks.

Adjust VR404 (A-1 μ S) so that the time marks coincide with the middle eight graticule marks.

HORIZONTAL AXIS ADJUSTMENT

GAIN ADJUSTMENT

Set the VOLTS/DIV switch to 10 mV. Set the TIME/DIV switch to X-Y. Set the COUPLING switch to AC.

Set the CH 1 AC-GND-DC Switch to AC. Set the SOURCE and VERT MODE switches to X-Y. Turn the CH 1 VOLTS/DIV VAR knob to CAL.

Connect the oscilloscope calibration generator to the CH 1 input connector, set for 1 kHz, 0.1 V p-p square-wave.

Adjust VR109 (X-GAIN) so that the trace is a ten division display.

Adjust the oscilloscope calibration generator for a two division display.

Pull out the X5 MAG control and check that the horizontal trace is within 10 ± 0.3 divisions on the CRT screen.

TRIGGER SYSTEM ADJUSTMENT

TRIGGER DC OFFSET ADJUSTMENT

Set the CH 1 [CH 2] AC-GND-DC switch to AC. Set the SOURCE and VERT MODE switches to CH 1 [CH 2]. Set the COUPLING switch to AC.

Set both the TIME/DIV switches to 10 mV. Set the sinewave generator for a 1 kHz, 80 mV p-p, eight division display signal.

Set the TIME/DIV switch to 1 mS. Turn the CH 1 [CH 2] POS control to the midposition.

Turn the POS control of LEVEL so that the trigger point is brought to the center of the displayed waveform amplitude.

Adjust VR110 [VR210] (TRIG DC OFFSET) until the position of the trigger point is not affected by alternate AC and DC positions of the COUPLING switch.

Repeat procedure for CH 2 using data shown in brackets.

1 DC OFFSET SIGNAL OUTPUT ADJUSTMENT

Set the VERT MODE switch to DUAL and the SOURCE switch to CH 1.

Set both the AC-GND-DC switches to GND.

Set the CH 2 VOLTS/DIV switch to 10 mV. Turn the CH 2 POS control to its midposition.

Using a coaxial cable, connect the CH 1 signal output to the CH 2 input terminal.

Change the CH 2 AC-GND-DC switch to DC.

Adjust VR112 (CH 1 OUT DC OFFSET) so that the trace is within ± 0.2 division of the center horizontal line.

POSITION ADJUSTMENT

Set the TIME/DIV switch to 1 mS.

Align the start point of the sweep with the left hand of the CRT graticule with the POS control of LEVEL.

Set the TIME/DIV switch to X-Y.

Adjust VR401 (X-DC) so that the beam spot is positioned at the center of the CRT graticule.

TRIGGER SLOPE BALANCE ADJUSTMENT

1. Set the VERT MODE switch to CH 1.
2. Turn the LEVEL VAR knob counterclockwise to FIX.
3. Set the TIME/DIV switch to 5 mS.
4. Connect the 1 kHz sinewave signal to the CH 1 input to get a 0.4 division display on the CRT screen.
5. Adjust VR403 (TRIG BAL) until the signal waveform has a steady and inverse waveform on the CRT screen when the operation is switched between + SLOPE and - SLOPE. (See example in Figs. 4 & 5)




Fig. 4. Adjusting Trigger Point




Fig. 5. Adjusting Trigger Point

CALIBRATOR OUTPUT ADJUSTMENT

CAL TERMINAL ADJUSTMENT

1. Set the VERT MODE switch to CH 1.
2. Set the CH 1 AC-GND-DC switch to DC. Set the CH 1 VOLTS/DIV switch to 0.5 V.
3. Set the TIME/DIV switch to 0.1 mS.
4. Using a coaxial cable, connect the CAL signal output to the CH 1 input terminal.
5. Adjust VR701 (1 kHz CAL) for a one-cycle Square-wave waveform aligned with the ten division graticule lines.

